

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004996/GSF3E2

Date: 20/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900255887
<b>Claimant Vehicle No :</b> SLS5555R	<b>Insured Vehicle No :</b> SMR1688K
Date of Loss: 03/04/2020	Nature of Claim: TP Claim No: 7190316370SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLS5555R</b>		
Make & Model:	TOYOTA ALPHARD, 2.4 G (A)	Engine No:	2AZF171172
Reg. Date:	22/07/2008 (Man. Year: 2008)	Chassis No:	ANH208003532
Colour:	Black	Odometer:	55191 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/45 R19	Rear Tyre Size:	235/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	06/04/2020	
Date Inspected:	07/04/2020 Inspected At:	Freesion Autodrive (Kaki Bukit) 25 Kaki Bukit Rd 4, Synergy @KB #03-33 Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL RH	Repair	0.00 F	*- F
2	1		*SLIDING DOOR RH	Buckled	0.00 F	*- F
3	1		*REAR BUMPER	Repair	0.00 F	*- F
4	1		*REAR RH FENDER	Repair	0.00 F	*- F
5	1		*REAR RH FENDER PROTECTOR	Cut	0.00 F	*- F
6	1		*REAR RH WHEEL RIM	Cut	0.00 F	*- F
7	1		*REAR RH WHEEL BEARING	* Check	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**