

ASS. REC. BY: Tanphu

REF:

SMD

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \$90K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLM8630T Yr Regn: 2017 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hairier c.c. 1986

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 64677 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZS4600095930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R17

R: 235/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 7/4/2023 40m

Survey held at Mom BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Rep. Form: \_\_\_\_\_

Lump Sum / L.B. (\$ \_\_\_\_\_)

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1006,  
Bukit Merah Lane 3,  
#01-04, 06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

04/04/2020

**SOMPO INSURANCE SINGAPORE PTE LTD**  
**50 RAFFLES PLACE**  
**#05-01/06 SINGAPORE LAND TOWER**  
**SINGAPORE 048623.**

Attention :- XA018

Page # :- 1

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

| No.                 | Description                    | Qty    | U.Price  | Amounts S\$        |
|---------------------|--------------------------------|--------|----------|--------------------|
| <b>LIST ITEMS :</b> |                                |        |          |                    |
| 1.                  | REAR WINDSCREEN GLASS - TBA    | 1 PC   |          |                    |
| 2.                  | REAR WINDSCREEN GLASS MOULDING | 1 PC   | 75.00    | 75.00 <i>nei</i>   |
| 3.                  | TAILGATE                       | 1 PC   | 2,125.00 | 2,125.00 <i>bc</i> |
| 4.                  | TAILGATE GARNISH               | 1 PC   | 555.00   | 555.00 <i>nei</i>  |
| 5.                  | TAILGATE LOGO                  | 1 PC   | 59.00    | 59.00 <i>nei</i>   |
| 6.                  | TAILGATE EMBLEM - HARRIER      | 1 PC   | 75.00    | 75.00 <i>nei</i>   |
| 7.                  | TAILGATE OUTER LAMP LH         | 1 PC   | 498.00   | 498.00 ?           |
| 8.                  | TAILGATE OUTER LAMP RH         | 1 PC   | 498.00   | 498.00 ?           |
| 9.                  | TAILGATE LOCK                  | 1 PC   | 435.00   | 435.00 ?           |
| 10.                 | TAILGATE LOCK COVER            | 1 PC   | 38.00    | 38.00 ?            |
| 11.                 | TAILGATE LOCK ANTENNA SENSOR   | 1 PC   | 116.00   | 116.00 ?           |
| 12.                 | TAILGATE RUBBER                | 1 PC   | 442.00   | 442.00 ?           |
| 13.                 | TAILGATE INNER TRIM LOWER      | 1 PC   | 676.00   | 676.00 ?           |
| 14.                 | TAILGATE INNER TRIM HANDLE LH  | 1 PC   | 50.00    | 50.00 x            |
| 15.                 | TAILGATE INNER TRIM HANDLE RH  | 1 PC   | 50.00    | 50.00 x            |
| 16.                 | TAILGATE STOPPER LH & RH       | 2 PCS  | 18.00    | 36.00 x            |
| 17.                 | TAILGATE ABSORBER LH - CHECK   | 1 PC   |          |                    |
| 18.                 | TAILGATE ABSORBER RH - CHECK   | 1 PC   |          |                    |
| 19.                 | TAILLAMP LH                    | 1 PC   |          |                    |
| 20.                 | TAILLAMP RH                    | 1 PC   |          |                    |
| 21.                 | TAILLAMP LOWER BRACKET LH      | 1 PC   | 117.00   | 117.00 ?           |
| 22.                 | TAILLAMP LOWER BRACKET RH      | 1 PC   | 117.00   | 117.00 ?           |
| 23.                 | TAILLAMP CLIP                  | 2 PCS  | 6.00     | 12.00 ?            |
| 24.                 | REAR BUMPER                    | 1 PC   | 1,415.00 | 1,415.00 <i>de</i> |
| 25.                 | REAR BUMPER LOWER              | 1 PC   | 465.00   | 465.00 ?           |
| 26.                 | REVERSE SENSOR                 | 1 PC   | 376.00   | 376.00 <i>nei</i>  |
| 27.                 | REAR BUMPER SIDE RETAINER LH   | 1 PC   | 93.00    | 93.00 <i>nei</i>   |
| 28.                 | REAR BUMPER SIDE RETAINER RH   | 1 PC   | 93.00    | 93.00 <i>nei</i>   |
| 29.                 | REAR BUMPER SPONGE             | 1 PC   | 125.00   | 125.00 ?           |
| 30.                 | REAR BUMPER CLIP               | 10 PCS | 5.00     | 50.00 <i>nei</i>   |
| 31.                 | END PANEL TOP GARNISH          | 1 PC   | 445.00   | 445.00 ?           |
| 32.                 | END PANEL - REPAIR             | 1 PC   |          |                    |
| 33.                 | SPARE TYRE PANEL - REPAIR      | 1 PC   |          |                    |
| 34.                 | TAILLAMP PANEL LH - REPAIR     | 1 PC   |          |                    |
| 35.                 | TAILLAMP PANEL RH - REPAIR     | 1 PC   |          |                    |
| 36.                 | REAR FENDER LH - REPAIR        | 1 PC   |          |                    |
| 37.                 | REAR FENDER RH - REPAIR        | 1 PC   |          |                    |
| 38.                 | REAR FENDER INNER TRIM LH      | 1 PC   | 649.00   | 649.00 x           |
| 39.                 | REAR FENDER INNER TRIM RH      | 1 PC   | 649.00   | 649.00 x           |
| LIST TOTAL S\$      |                                |        |          | 10,334.00          |
| 25% DISCOUNT S\$    |                                |        |          | -2,583.50          |
|                     |                                |        |          | <hr/> 7,750.50     |

**SPECIAL NET ITEMS :**

|    |                   |      |       |                  |
|----|-------------------|------|-------|------------------|
| 1. | SEALANT           | 1 PC | 40.00 | 40.00 <i>nei</i> |
| 2. | REAR NUMBER PLATE | 1 PC | 40.00 | 40.00 <i>nei</i> |



Automotive Pte Ltd

**Main Office:**

Mova Building  
No. 22 Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 3891  
www.mova.com.sg

**Workshop Dept:**

Block 1008  
Bukit Merah Lane 3,  
#01-04/05/06/07  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6271 3891  
Co. Reg: 196904033G  
GST Reg: MO1068864-2

Page # :- 1 138024

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

# Estimate

04/04/2020

**SOMPO INSURANCE SINGAPORE PTE LTD**  
**50 RAFFLES PLACE**  
**#05-01/06 SINGAPORE LAND TOWER**  
**SINGAPORE 048623.**

Attention :- XA018

| No. | Description                                                                                                                      | Qty                 | U.Price  | Amounts S\$ |
|-----|----------------------------------------------------------------------------------------------------------------------------------|---------------------|----------|-------------|
|     | SPECIAL NET TOTAL S\$                                                                                                            |                     |          | 80.00       |
|     | <b>LABOUR :</b>                                                                                                                  |                     |          |             |
|     | TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING                                                                                | 60                  | 80.00    | 80.00       |
|     | TO REPLACE REVERSE SENSOR & DIAGNOSE FUNCTION                                                                                    | 30                  | 80.00    | 80.00       |
|     | TO REPAIR ON END PANEL, SPARE TYRE PANEL, BOTH TAILLAMP PANEL, REAR FENDER LH & RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION | 700                 | 900.00   | 900.00      |
|     | TO REMOVE & TRANSFER REAR WINDSCREEN GLASS INTO NEW TAILGATE                                                                     | 120                 | 150.00   | 150.00      |
|     | TO REMOVE & REFIT REAR COMPARTMENT & FITTING                                                                                     | 60                  | 150.00   | 150.00      |
|     | TO SPRAY PAINT ON REPAIRED AREAS                                                                                                 | <del>700</del> 1000 | 1,200.00 | 1,200.00    |
|     | TO RUST PROOF ON REPAIRED AREAS                                                                                                  | 60                  | 150.00   | 150.00      |
|     | TO APPLY BODY JOINT SEALANT ON REPAIRED AREAS                                                                                    | 60                  | 80.00    | 80.00       |
|     | <b>LABOUR TOTAL S\$</b>                                                                                                          |                     |          | 2,790.00    |

E. & O.E

**NON-TAX AMOUNT S**

AMOUNT S\$ 10,620.50

GST @ 7 % 743.44

AMOUNT DUE S\$ 11,363.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Acknowledged by Repairer

Signature:

Date:

Taukh 97495719  
WP 7/4/202  
6 days 340pm  
tauakh@khant.com  
Lumpsum 10%