

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005007/UEA3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLR5914T	Insured Vehicle No :	GBH169G
Date of Loss:	03/04/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR5914T	Engine No:	2NRX165924
Make & Model:	TOYOTA VIOS, 1.5 E CVT (A)	Chassis No:	MHFB29F3002013106
Reg. Date:	21/08/2017 (Man. Year: 2017)	Odometer:	51731 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,070.18	1,428.05	2,642.13	64.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,590.00	740.00	31.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,400.18	3,018.05	3,382.13	52.84
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	6,400.18	2,400.00	4,000.18	62.50
+ GST 7.00/7.00% (S\$)	448.01	168.00	280.01	62.50
Nett Amount (S\$)	6,848.19	2,568.00	4,280.19	62.50
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,075.45		

INSPECTION

Date of Assignment: 29/07/2020

Date Inspected: 29/07/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5914T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	967.54 FL	*645.10 FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	98.50 FL	*- FL
3	1		*REAR FENDER RH	Dented / Bent	1,072.54 FL	*1,072.54 FL
4	1		*REAR WHEEL HOUSING RH	Not Necessary	827.60 FL	*- FL
5	1		*REAR DOOR RH	Repair	1,270.51 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	219.55 FL	*133.10 FL
7	1		*REAR DOOR HANDLE RH (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*REAR ROCKER PANEL RH (NPA)	Repair	0.00 FS	*- FS
9	1		*REAR WHEEL RIM RH	Repair	680.00 FS	*- FS
10	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,184.24	1,890.74
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,114.06	462.69
Total Parts (\$\$)	4,070.18	1,428.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	680.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	700.00
3	ANTI-RUST COATING	New	150.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	0.00
6	TO REMOVE & REFIT CUSHION & UPHOLSTERY	New	150.00	60.00
Gross Labour Cost (\$)			2,330.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >