Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005009/BPA3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100496456

Claimant
Vehicle No: SMC1590L Insured Vehicle No: SCV816L

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 3961732513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC1590L

 Make & Model:
 TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)
 Engine No:
 2ZR0B74991

 Reg. Date:
 27/06/2018 (Man. Year: 2018)
 Chassis No:
 ZVW400029572

 Colour:
 Black
 Odometer:
 165938 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,034.97	4,342.77	2,692.20	38.27
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,070.00	1,640.00	1,430.00	46.58
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,104.97	5,982.77	4,122.20	40.79
	Approved Total (Overridden) (S\$)		4,750.00		
	Nett Amount (S\$)	10,104.97	4,750.00	5,354.97	52.99
	+ Loss of Use (3.0 x S\$	60.00/day) (S\$)	180.00		
	+ Car Rental (4.0 x S\$120.00/day + 7.	00% GST) (S\$)	513.60		
	+ Doc/S	earch Fee (S\$)	29.00		
	Ne	tt Liability (S\$)	5,472.60		
	Global Sum S	Settlement (S\$)	5,470.00		

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 13/04/2020 Inspected At: Team Autopro Pte Ltd (Sin Ming)

385 Sin Ming Drive, #01-02 Vicom

Inspection Centre Singapore 575718

Estimated Period of Repair: 6.0 days

Adjuster Report Page 2 of 4

Adjuster: Lim Teow Guan Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	789.50 FL	*665.10 FL
2	1		*FRONT BUMPER INNER SPONGE	Broken	358.20 FL	*187.10 FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	290.00 FL	*156.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	410.50 FL	*- FL
5	1		*FRONT BUMPER GRILLE LOWER	Broken	426.80 FL	*426.80 FL
6	1		*FRONT BUMPER LID	No such part	218.60 FL	*- FL
7	2		*FRONT BUMPER SIDE GARNISH	No such part	649.00 FL	*- FL
8	1		*FRONT BUMPER INNER RUBBER	Not Damaged	84.00 FL	*- FL
9	1		*FRONT UPPER GRILLE	Broken	189.70 FL	*189.70 FL
10	1		*FRONT LOGO	Necessary	135.00 FL	*117.00 FL
11	1		*FRONT RADAR SENSOR	Scratched	1,842.60 FL	*1,500.00 FL
12	1		*FRONT TOW CAP	O/S Dislodged	202.00 FL	*73.00 FL
13	1		*FRONT FOG LAMP	O/S Broken	592.00 FL	*296.00 FL
14	1		*FRONT LICENSE PLATE	Not Damaged	78.60 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	128.00 FL	*128.00 FL
16	2		*HEADLAMP	Broken	1,957.20 FL	*1,825.00 FL
17	2		*HEADLAMP LOWER BRACKET	Not Damaged	481.60 FL	*- FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*-FS
19	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT BUMPER SIDE RETAINER CLIPS	Not Necessary	50.00 FS	*-FS
21	1		*FRONT UPPER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*FRONT LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*FRONT NUMBER PLATE WITH GARNISH	Broken	80.00 FS	*50.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	•	5,733.70
			- List Item Discount on L Items 2	25.00/25.00% (S\$)	2,208.33	1,390.93
				Total Parts (S\$)	7,034.97	4,342.77

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEAT	New	1,200.00	800.00
2	RUST PROOFING	New	100.00	30.00
3	RADAR SENSOR ALIGNMENT	New	300.00	300.00
4	TO DIAGNOTIC RESET FAULT CODE	New	150.00	60.00
5	SPRAY PAINTING	New	1,200.00	400.00
6	CHECK WIRING	New	120.00	50.00
		Gross Labour Cost (S\$)	3,070.00	1,640.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >