

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20005013/BGA3Q2**Date:** 18/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800041906
<b>Claimant Vehicle No :</b>	SML3788Z	<b>Insured Vehicle No :</b>	ED47K
Date of Loss:	06/04/2020	Nature of Claim:	TP
		Claim No:	1415459554SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML3788Z</b>	Engine No:	G4FGKU153678
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU917070
Reg. Date:	17/05/2019 (Man. Year: 2019)	Odometer:	25387 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,433.20	9,244.88	4,188.32	31.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,420.00	1,580.00	39.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,433.20</b>	<b>11,664.88</b>	<b>5,768.32</b>	<b>33.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,220.32</b>	<b>816.54</b>	<b>403.78</b>	<b>33.09</b>

<b>Nett Amount (S\$)</b>	<b>18,653.52</b>	<b>12,481.42</b>	<b>6,172.10</b>	<b>33.09</b>
<b>+ Loss of Use (13.0 x S\$60.00/day) (S\$)</b>		780.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>+ Other Costs (S\$)</b>		90.00		
<b>Nett Liability (S\$)</b>		<b>13,387.87</b>		

INSPECTION

Date of Assignment: 07/04/2020

Date Inspected: 08/04/2020

Estimated Period of Repair: 9.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)  
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY  
 Singapore 575722

**Adjuster:** Lim Teow Guan**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,052.00 FL	*1,052.00 FL
2	1		*BONNET LOCK	Jammed	84.30 FL	*84.30 FL
3	2		*BONNET HINGE	Not Damaged	190.80 FL	*- FL
4	1		*FRONT GRILLE	Broken	683.20 FL	*460.20 FL
5	1		*FRONT GRILLE LOGO	Necessary	139.50 FL	*71.00 FL
6	1		*FRONT LICENCE PLATE	Broken	120.50 FL	*69.00 FL
7	1		*FRONT BUMPER	Broken	1,486.90 FL	*785.80 FL
8	1		*FRONT BUMPER LOWER LIP	Bent	346.20 FL	*265.00 FL
9	1		*FRONT BUMPER RUBBER	Torn	84.30 FL	*84.30 FL
10	2		*FRONT BUMPER SIDE RETAINER	Necessary	318.80 FL	*173.80 FL
11	2		*FRONT BUMPER FOG LAMP	Not Necessary	772.20 FL	*- FL
12	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	213.00 FL	*- FL
13	1		*FRONT BUMPER INNER SPONGE	Broken	264.70 FL	*264.70 FL
14	1		*FRONT BUMPER REINFORCEMENT	Dented	652.80 FL	*589.50 FL
15	2		*HEADLAMP	Broken	3,787.00 FL	*3,787.00 FL
16	2		*HEADLAMP LOWER BRACKET	Broken	428.60 FL	*197.20 FL
17	1		*FRONT SUPPORT PANEL	Broken	859.50 FL	*859.50 FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	No such part	204.00 FL	*- FL
19	1		*AIR CON CONDENSOR	Broken	947.60 FL	*819.60 FL
20	1		*RADIATOR	Bent	865.20 FL	*561.90 FL
21	1		*FRONT FENDER	N/S Dented	1,571.20 FL	*785.60 FL
22	1		*FRONT FENDER INNER COWLING	O/S Torn	569.20 FL	*195.70 FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*BONNET SEALANT	Necessary	100.00 FS	*30.00 FS
25	1		*BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
26	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT GRILLE CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*AIR CON FLUID	Necessary	80.00 FS	*40.00 FS
29	1		*RADIATOR COOLANT	Necessary	80.00 FS	*50.00 FS
30	1		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
31	2		*FRONT FENDER SEALANT	Necessary	200.00 FS	*100.00 FS
32	2		*FRONT FENDER INNER COWLING CLIP	Necessary	100.00 FS	*30.00 FS
33	1		*FRONT NUMBER PLATE W/COWLING	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$)**
**16,561.50**
**11,466.10**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINT	New	1,600.00	1,000.00
3	R&R RADIATOR	New	150.00	80.00
4	R&R AIR CON CONDENSOR	New	150.00	80.00
5	UPHOLSTERY	New	200.00	0.00
6	CHECK WIRING	New	100.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >