

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005014/BBA3Q2

Date: 13/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100307901-07

Claimant
Vehicle No : SGS7761H **Insured Vehicle No :** SKF9036B

Date of Loss: 30/03/2020 Nature of Claim: TP Claim No: 4135478477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS7761H		
Make & Model:	HONDA ACCORD, 2.0 (A)	Engine No:	K20A6043728
Reg. Date:	23/03/2017 (Man. Year: 2016)	Chassis No:	CL73203215
Colour:	Brown	Odometer:	194339 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,460.32	2,451.68	2,008.64	45.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	850.00	1,400.00	62.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,710.32	3,301.68	3,408.64	50.80
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	6,710.32	2,650.00	4,060.32	60.51
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Car Rental (2.0 x S\$140.00/day) (S\$)		280.00		
Nett Liability (S\$)		3,250.00		

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 08/04/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,087.60 FL	*1,087.60 FL
2	2		*FRONT BUMPER RETAINER	Necessary	168.40 FL	*76.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	351.00 FL	*- FL
4	1		*FRONT BUMPER SIDE GARNISH	No such part	88.30 FL	*- FL
5	1		*FRONT BUMPER LOWER LIP	Not Damaged	410.60 FL	*- FL
6	1		*FRONT BUMPER CENTER GRILLE	Cut	685.40 FL	*350.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Dislodged	358.60 FL	*250.00 FL
8	1		*FRONT GRILLE LOGO	Necessary	84.00 FL	*84.00 FL
9	1		*HEADLAMP LH	Cut	1,042.00 FL	*1,042.00 FL
10	1		*HEADLAMP LOWER BRACKET LH	Not Damaged	204.00 FL	*- FL
11	1		*FRONT FENDER LH	Not Damaged	608.00 FL	*- FL
12	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
13	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
14	1		*FRONT BUMPER CENTER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT NO PLATE W/COWLING	Necessary	80.00 FS	*50.00 FS
17	1		*FRONT FENDER SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,477.90	3,029.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,017.58	577.92
Total Parts (\$\$)	4,460.32	2,451.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	1,000.00	600.00
2	CHECK WIRING	New	100.00	50.00
3	RUST PROOFING	New	150.00	0.00
4	SPRAY PAINTING	New	1,000.00	200.00
Gross Labour Cost (\$\$)			2,250.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >