Adjuster Report Page 1 of 5

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20005017/KSF3E2

Date: 14/04/2020

**REFERENCE** 

No:

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MU008483 Claimant Vehicle SHC5825T Insured Vehicle No: SKK6241T

Nature of Claim: ΤP Date of Loss: 01/04/2020 Claim No: M2002374

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC5825T

Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002208 Reg. Date: 11/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280332

Colour: Metallic White/Red Odometer: 623871 km

**Engine Capacity:** 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: Rear Tyre Size: 215/60 R16 215/60 R16 Front Left Side: Rear Left Side: Sailun 9 mm Sailun 8 mm Front Right Side: Rear Right Side: Sailun 9 mm Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,372.21	45.00	12,327.21	99.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,000.00	280.00	13,720.00	98.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,372.21	325.00	26,047.21	98.77
+ GST 7.00/7.00% (S\$)	1,846.05	22.75	1,823.30	98.77
Nett Amount (S\$)	28,218.26	347.75	27,870.51	98.77

**INSPECTION** 

Date of Assignment: 08/04/2020

Date Inspected: 06/04/2020 Trans-Cab Services Pte Ltd (HQ) Inspected At:

2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG Manager: Hiew May Fung Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Apr 2020)

Parts: 143 RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SHC5825T)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

Nο	Otv	Dart No	. Particulars	Condition	Repairer's	Reference	Amount
		rait NO			-		
1	1		*BUMPER COVER FRT	Repair	747.20 FL		*- FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL		*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL		*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL		*-FL
5	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL		*-FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL		*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL		*-FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL		*- FL
9	1		*BUMPER BEAM FRT	Repair	663.70 FL		*-FL
10	1		*TOW COVER FRT	Serviceable	60.90 FL		*- FL
11	1		*FRONT BRACE PANEL	Repair	177.22 FL	-	*- FL
12	1		*RADIATOR GRILLE	Serviceable	969.90 FL		*- FL
13	1		*RADIATOR GRILLE BADGE RENAULT	Not Necessary			*- FL
14	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	-	*- FL
15	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	-	*- FL
16	1		*FRAME FULL SUPPORT BRACKET	Serviceable	41.60 FL	-	*- FL
17	1		*HEADLAMP LH	Serviceable	743.60 FL	-	*- FL
18	1		*HEADLAMP RH	Serviceable	743.60 FL	-	*- FL
19	1		*HEADLAMP PANEL FRT LH	Repair	127.70 FL	-	*- FL
20	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	-	*- FL
21	1		*BONNET	Repair	1,312.70 FL	-	*- FL
22	1		*BONNET INSULATOR	Serviceable	294.30 FL	-	*- FL
23	1		*BONNET STRUT LH	Serviceable	53.30 FL	-	*- FL
24	1		*BONNET STRUT RH	Serviceable	53.30 FL	-	*- FL
25	1		*BONNET HINGE LH	Repair	236.50 FL	-	*- FL
26	1		*BONNET HINGE RH	Repair	237.40 FL	-	*- FL
27	1		*BONNET LOCK	Repair	152.80 FL	-	*- FL
28	1		*FENDER PANEL FRT LH	Repair	414.40 FL	-	*- FL
29	1		*WHEELARCH FRT LH	Serviceable	112.30 FL	-	*- FL
30	1		*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	-	*- FL
31	1		*FENDER PANEL FRT RH	Repair	437.10 FL	-	*- FL
32	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	-	*- FL
33	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	-	*- FL
34	1		*WIPER RESERVOIR	Serviceable	179.60 FL	-	*- FL
35	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	-	*- FL
36	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	-	*- FL
37	1		*AIR CLEANER BOX	Serviceable	464.20 FL	-	*- FL
38	1		*AIR CLEANER HOSE	Serviceable	175.85 FL		*- FL
39	1		*AIR CLEANER LOWER	Serviceable	271.26 FL		*- FL

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
40	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	-	*- FS
41	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	-	*- FS
42	1		*SET BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	_	*- FS
43	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	-	*- FS
44	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	-	*- FS
45	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	-	*- FS
46	1		*RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	_	*- FS
47	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	_	*- FS
48	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	_	*- FS
49	1		*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	-	*- FS
50	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	_	*- FS
51	1		*FRONT RENAULT TYRE 215/60/16	Not Necessary	300.00 FS	_	*- FS
52	1		*FRONT RENAULT TYRE RIM	Not Necessary	380.00 FS	_	*- FS
53	1		*FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	-	*45.00 FS
54	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	_	*- FS
55	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	-	*- FS
56	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	-	*- FL
F=Fra	anchise	part. S=Spo	Nett. L=ListItemDisc.				-
				Sub Total (S\$)	13,614.79	45.00	
			- List Item Discount on L Items 10	.00/10.00% (S\$)	1,242.58	0.00	
				Total Parts (S\$)	12,372.21		45.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	60.00
4	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
	Gross Labou	r Cost (S\$)	14,000.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >