

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003961/T1BA3Q2-1

Date: 05/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507735

Claimant
Vehicle No : SMJ1452R **Insured Vehicle No :** SDH8381H

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 2846567801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMJ1452R | Engine No: | CZC692205 |
| Make & Model: | VOLKSWAGEN GOLF, 1.4 TSI HL (A) | Chassis No: | WVWZZZAUZKW063780 |
| Reg. Date: | 22/02/2019 (Man. Year: 2018) | Odometer: | 5331 km |
| Colour: | Black | | |
| Engine Capacity: | 1395 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 225/40 R18 | Rear Tyre Size: | 225/40 R18 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 4,163.85 | 3,220.46 | 943.39 | 22.66 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 9,490.00 | 4,540.00 | 4,950.00 | 52.16 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 13,653.85 | 7,760.46 | 5,893.39 | 43.16 |
| + GST 7.00/7.00% (S\$) | 955.77 | 543.23 | 412.54 | 43.16 |
| Nett Amount (S\$) | 14,609.62 | 8,303.69 | 6,305.93 | 43.16 |
| + Car Rental (6.0 x S\$80.00/day + 7.00% GST) (S\$) | | 513.60 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 8,819.29 | | |

INSPECTION

Date of Assignment: 12/03/2020

Date Inspected: 12/03/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|---|---------------|-----------------|-----------------|
| 1 | 1 | | *COVER FOR BUMPER PRIMED | Deformed | 1,124.14 FS | *1,124.14 FS |
| 2 | 1 | | *GUIDE PIECE (REAR BUMPER ,GUIDE RHS) | *Check | 36.38 FS | *- FS |
| 3 | 1 | | *GUIDE PIECE (REAR BUMPER ,BRACKET RHS) | *Check | 36.38 FS | *- FS |
| 4 | 1 | | *RUBBER VALVE | Necessary | 3.29 FS | *3.29 FS |
| 5 | 1 | | *WHEELHOUSE PROTECTOR | Not Necessary | 233.93 FS | *- FS |
| 6 | 1 | | *LED TAIL LIGHT (RHR OUTER TAILLIGHT) | Not Necessary | 567.32 FS | *- FS |
| 7 | 1 | | *WHEEL DISC ALUM WITH | Cut | 1,909.39 FS | *1,909.39 FS |
| 8 | 2 | | *SENSOR BRACKET | Necessary | 23.80 FS | *23.80 FS |
| 9 | 1 | | *SENSOR BRACKET | Necessary | 11.90 FS | *11.90 FS |
| 10 | 1 | | *SENSOR BRACKET | Necessary | 12.60 FS | *12.60 FS |
| 11 | 1 | | *2K-PLASTIC ADHESIVE | Necessary | 75.94 FS | *75.94 FS |
| 12 | 1 | | *BONDING AGENT FOR PLASTIC | Necessary | 59.40 FS | *59.40 FS |
| 13 | 1 | | *REFLECTOR RH | Not Necessary | 69.38 FS | *- FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (S\$) | | | | | 4,163.85 | 3,220.46 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|-------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | DIAGNOSTIC AND PROGRAMMING | New | 480.00 | 480.00 |
| 2 | CHECK SHORT CIRCUIT /HARNESS REPAIR | New | 360.00 | 360.00 |
| 3 | WHEEL ALIGNMENT | New | 360.00 | 0.00 |
| 4 | R&R RIM & BALANCE | New | 50.00 | 0.00 |
| 5 | LABOUR | New | 4,200.00 | 1,680.00 |
| 6 | SPRAY PAINTING | New | 3,200.00 | 1,600.00 |
| 7 | R&R REAR LUGGAGE TRIM | New | 840.00 | 420.00 |
| Gross Labour Cost (\$\$) | | | 9,490.00 | 4,540.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >