

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005030/QRS3Q2
Date: 17/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMG8059M	Insured Vehicle No :	SHC8385B
Date of Loss:	04/04/2020	Nature of Claim:	TP
		Claim No:	MCT20040051

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8059M		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YE43716
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG112265
Colour:	Silver	Odometer:	28479 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,217.36	1,545.84	671.52	30.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	986.84	911.84	75.00	7.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,204.20	2,457.68	746.52	23.30
+ GST 7.00/7.00% (S\$)	224.29	172.04	52.25	23.30

Nett Amount (S\$)	3,428.49	2,629.72	798.77	23.30
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
Nett Liability (S\$)		3,014.92		

INSPECTION

Date of Assignment: 07/04/2020

Date Inspected: 20/04/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Hua Hong Pte Ltd (Sungei Kadut)
25D Sungei Kadut Street 1
Singapore 729332

Adjuster: OI SUN PIN**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG8059M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R REFLECTOR (WCP)	Not Necessary	151.47 F	*- F
2	1		*REAR BUMPER (WCP)	Crumpled	875.72 F	*875.72 F
3	1		*REAR BUMPER SUPPORT (WCP)	Not Necessary	392.70 F	*- F
4	1		*REAR PANEL (WCP)	Dented	426.36 F	*426.36 F
5	1		*RR BUMPER CLAMP KIT (WCP)	Necessary	43.76 F	*43.76 F
6	1		*RR BUMPER PROTECTION (WCP)	Not Necessary	106.59 F	*- F
7	1		*TOWING EYE COVER (WCP)	Not Necessary	20.76 F	*- F
8	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
Total Parts (S\$)					2,217.36	1,545.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	98.0 WUX50.00 SGD/H	New	490.00	415.00
2	LABOUR COST 74.0 WU X 50.00 SGD/H	New	370.00	370.00
3	MATERIAL COST	New	126.84	126.84
Gross Labour Cost (\$\$)			986.84	911.84

Report was unsubmitted during this print-out.

< END OF ESTIMATES >