

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005033/KGA3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100364747
Claimant
Vehicle No : SGK1177B **Insured Vehicle No :** SDU8908X
 Date of Loss: 31/03/2020 Nature of Claim: TP Claim No: 1265879463SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK1177B**
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: LEB5904470
 Reg. Date: 16/06/2016 (Man. Year: 2016) Chassis No: RU31204460
 Colour: Metallic Grey Odometer: 148087 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Dunlop 2 mm Rear Left Side: Dunlop 2 mm
 Front Right Side: Dunlop 2 mm Rear Right Side: Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,359.76	587.04	772.72	56.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	1,080.00	330.00	23.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,769.76	1,667.04	1,102.72	39.81
+ GST 7.00/7.00% (S\$)	193.88	116.69	77.19	39.81
Nett Amount (S\$)	2,963.64	1,783.73	1,179.91	39.81
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
		(S\$) 2,211.73		
Liabe Amount (50.00%) (S\$)		1,105.87		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,107.87		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment: 09/04/2020
 Date Inspected: 09/04/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
 6 Kung Chong Road
 Singapore 159143
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	405.20 FL	*405.20 FL
2	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	68.50 FL	*68.50 FL
3	8		*FRONT FENDER INNER LINER CLIPS	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT FENDER EXTENSION COVER RH	Dented / Distorted	172.10 FL	*172.10 FL
5	1		*FRONT BUMPER SIDE BRACKER RH	Serviceable	29.50 FL	*- FL
6	1		*FRONT DOOR RH	Repair	936.40 FL	*- FL
7	8		*FRONT BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
8	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,699.70	733.80
- List Item Discount on L Items 20.00/20.00% (\$)	339.94	146.76
Total Parts (\$)	1,359.76	587.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPAIR ,REPLACE ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	480.00	400.00
2	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF FRONT DOOR RH	New	120.00	0.00
3	LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC	New	60.00	0.00
4	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIAL AT FRONT BUMPER ,FRONT FENDER RH & FRONT DOOR RH	New	750.00	680.00
Gross Labour Cost (\$\$)			1,410.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >