

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|  | Reg. No: 199607198R GST Reg. No. 19-9607198-R   |   |                  |            |  |
|--|---|---|------------------|------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile                                |   |   |                  |            |  |
| AUT  | AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI20005039/Utf3e2  |   |                  |            |  |
| (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 |   |   | Date: 20-04-2020 |            |  |
|  |   |   | Code: AGI        |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |   |   |                  |            |  |
|  | Insured Veh.  | SLS 2057G   | Veh. Inspected   | GBJ 8181G  |  |
|  | Policy No.  |   | Coverage (\$)    | 0.00       |  |
|  | Claim No.   | C10006110   | Excess (\$)      | 0.00       |  |
|  | Assign From   | IVY RATILLA   | Assign Date      | 07/04/2020 |  |
| 2. Vehicle Particulars & Condition   |   |   |                  |            |  |
|  | Make & Model  | TOYOTA DYNA (M)   | c.c              | 2982       |  |
|  | Engine No.  | HIDDEN  | Year of Reg.     | 2010       |  |
|  | Chassis No.   | JTFAT35Y60K201358   | Colour           | WHITE      |  |
|  | Odometer  | 288751  | Steering         | IN ORDER   |  |
|  | Brakes  | IN ORDER  | Modification     | NIL        |  |
|  | General   | GOOD  |                  |            |  |
| 3. Conditions of Tyres   |   |   |                  |            |  |
|  |   | Size  | Make             | Balance    |  |
|  | R/H Front Tyre  | 195 R15   | BRIDGESTONE      | 5 mm       |  |
|  | L/H Front Tyre  |   |                  | mm         |  |
|  | R/H Rear Tyre   | 155 R12 (D)   | BRIDGESTONE      | 5/5 mm     |  |
|  | L/H Rear Tyre   |   |                  | mm         |  |
| 4.   | 4. Description of Damages   |   |                  |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  |   |                  |            |  |
|  | DAMAGES SEE DETAILS.  |   |                  |            |  |
| 5.   | 5. General Information  |   |                  |            |  |
|  | Accident Date   | 04/04/2020  | Inspection Date  | 07/04/2020 |  |
|  | Survey held at  | FOCUS AUTO PTE LTD  |                  |            |  |
|  |   | NO 1 KAKI BUKIT AVE 6<br>AUTOBAY #02-48<br>SINGAPORE 417883 |                  |            |  |
| 5a.  |   |   |                  |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                  |            |  |
| 5b.  | <b>b.</b> Estimate Days of Repair   |   |                  |            |  |
| FOTIMATED NORMAL DEDICE FOR DEDAID.  |   |   |                  |            |  |

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: