

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20005045/R1VF3E2

Date: 14/08/2020

REFERENCE

Insured/Claimant:	TAN AIK NA	Policy No:	1800067098
Date of Loss:	30/03/2020	Nature of Claim:	OD
		Claim No:	0169805002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ318M		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX030318
Reg. Date:	12/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF8J2121246
Colour:	Black	Odometer:	40874 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$154,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,940.00	6,950.16	12,989.84	65.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,272.00	2,672.00	2,600.00	49.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,212.00	9,622.16	15,589.84	61.83
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	24,212.00	8,622.16	15,589.84	64.39
+ GST 7.00/7.00% (\$\$)	1,694.84	603.55	1,091.29	64.39
Nett Amount (\$\$)	25,906.84	9,225.71	16,681.13	64.39

INSPECTION

Date of Assignment:	07/04/2020	
Date Inspected:	06/04/2020	Inspected At:
		281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,445.00 FS	*1,956.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	254.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - RH	Serviceable	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Serviceable	105.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTRE	Serviceable	134.00 FS	*- FS
6	1		*FRONT BUMPER FRONT SPOILER	Cracked	709.00 FS	*567.20 FS
7	1		*FRONT BUMPER UNDERRUN BAR	Serviceable	447.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	161.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	3,327.00 FS	*2,661.60 FS
10	1		*QUATTRO INSCRIPTION	Necessary	90.00 FS	*71.76 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Serviceable	230.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	537.00 FS	*429.60 FS
13	1		*FRONT BUMPER END CAP - RH	Serviceable	86.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Serviceable	857.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	269.00 FS	*215.20 FS
16	1		*FOAM FILLER PIECE COVER	Serviceable	120.00 FS	*- FS
17	1		*FRONT BUMPER GUIDE SECTION - RH	Serviceable	36.00 FS	*- FS
18	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
19	1		*AIRCON STICKER	Not Necessary	18.00 FS	*- FS
20	1		*HORN - RH HIGH TONE	Not Necessary	184.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Serviceable	0.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
23	1		*WHEEL HOUSING LINER - RH	Serviceable	248.00 FS	*- FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT	Not Necessary	36.00 FS	*- FS
25	1		*WHEEL SPOILER	Serviceable	146.00 FS	*- FS
26	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,190.00 FS	*952.00 FS
27	1		*HEADLIGHT MOUNTING - RH	Serviceable	112.00 FS	*- FS
28	1		*LED HEADLIGHT - RH	Serviceable	7,462.00 FS	*- FS
29	1		*LIFT CYLINDER - RH	Serviceable	132.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - RH	Serviceable	53.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE - CENTRE	Serviceable	40.00 FS	*- FS
32	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Serviceable	90.00 FS	*- FS
33	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Necessary	300.00 FS	*36.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,940.00 6,950.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,272.00	2,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >