

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005065/UUF3E2

Date: 30/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19237719000
Claimant Vehicle No :	SKU7567U	Insured Vehicle No :	GBJ8710E
Date of Loss:	03/04/2020	Nature of Claim:	TP
		Claim No:	SNM20D201670

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU7567U	Engine No:	L15B4021163
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11101162
Reg. Date:	14/08/2015 (Man. Year: 2015)	Odometer:	104257 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,167.06	4,480.24	5,686.82	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,995.00	2,060.00	935.00	31.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,162.06	6,540.24	6,621.82	50.31
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	13,162.06	5,200.00	7,962.06	60.49
+ GST 7.00/7.00% (S\$)	921.34	364.00	557.34	60.49
Nett Amount (S\$)	14,083.40	5,564.00	8,519.40	60.49

INSPECTION

Date of Assignment: 07/04/2020
 Date Inspected: 08/04/2020 Inspected At:

Yew Tee Automobile Tech Pte Ltd
 (Woodlands)
 39 Woodlands Close #01-12,
 Mega@Woodlands
 Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Apr 2020)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU7567U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,156.20 FL	*798.10 FL
2	1		*REAR BUMPER BRACKET LH	Not Necessary	36.40 FL	*- FL
3	1		*REAR BUMPER BRACKET RH	Not Necessary	36.40 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	42.30 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	42.30 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	180.60 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Not Necessary	180.60 FL	*- FL
8	1		*REAR BUMPER CORNER GARNISH RH	Torn	282.10 FL	*282.10 FL
9	1		*REAR BUMPER CORNER GARNISH LH	Torn	282.10 FL	*282.10 FL
10	1		*REAR TAILGATE	Badly Dented	1,440.30 FL	*953.00 FL
11	1		*REAR TAILGATE H EMBLEM	Necessary	54.20 FL	*35.80 FL
12	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	54.20 FL	*54.20 FL
13	1		*REAR TAILGATE OUTER GARNISH	Cracked	276.30 FL	*276.30 FL
14	1		*REAR BOOT LID LAMP RH	Cracked	305.10 FL	*305.10 FL
15	1		*REAR BOOT LID LAMP LH	Cracked	305.10 FL	*305.10 FL
16	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	386.40 FL	*- FL
17	1		*REAR TAILGATE LOCK	Twisted	238.20 FL	*198.50 FL
18	1		*REAR TAILGATE LOCK CABLE	Not Necessary	156.10 FL	*- FL
19	1		*REAR TAILGATE LOCK CATCH	Not Necessary	23.70 FL	*- FL
20	1		*REAR TAIL GATE RUBBER	Twisted	184.40 FL	*184.40 FL
21	1		*REAR END PANEL	Badly Dented	636.80 FL	*514.00 FL
22	1		*REAR END PANEL TOP GARNISH	Torn	128.60 FL	*128.60 FL
23	1		*REAR SPARE TYRE BOARD	Serviceable	462.30 FL	*- FL
24	1		*REAR SPARE TYRE PANEL	Repair	1,356.80 FL	*- FL
25	1		*REAR SPARE TYRE TOOLS SPONGE	Not Necessary	462.80 FL	*- FL
26	1		*REAR TAIL LAMP RH	Cracked	564.30 FL	*441.50 FL
27	1		*REAR TAIL LAMP LH	Cracked	564.30 FL	*441.50 FL
28	1		*REAR TAIL LAMP LOWER PANEL LH	Not Necessary	163.10 FL	*- FL
29	1		*REAR TAIL LAMP LOWER PANEL RH	Not Necessary	163.10 FL	*- FL
30	1		*REAR END PANEL KEYLESS SENSOR	Not Necessary	202.68 FL	*- FL
31	1		*REAR EXHAUST PIPE	Not Necessary	1,020.10 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	151.30 FL	*- FL
33	1		*REAR EXHAUST MOUNTING	Not Necessary	38.40 FL	*- FL
34	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*REAR TAIL GATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
38	1		*REAR BUMPER REVERSE SENSORS	Shorted	500.00 FS	*200.00 FS
39	1		*REAR CARPLATE	Serviceable	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR CARPLATE LAMP	Not Necessary	160.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,482.58	5,520.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,315.52	1,040.06
Total Parts (\$\$)					10,167.06	4,480.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	150.00	80.00
2	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	0.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
4	TO TRANSFER REAR TAILGATE	New	100.00	60.00
5	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	800.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION }	New	50.00	50.00
8	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION }	New	100.00	0.00
9	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	0.00
10	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	950.00	900.00
11	TO DO UP INTERIOR CLEANING AND CHEMICAL WASH	New	200.00	0.00
Gross Labour Cost (\$\$)			2,995.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >