

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2454A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER BEAM	NOT NECESSARY	294.80	-
1	REAR BUMPER CTR MOULDING	CRACKED	451.25	451.25
1	REAR BUMPER LWR MOULDING	DEFORMED	155.00	155.00
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER BEAM STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER BEAM STAY RH	NOT NECESSARY	138.10	-
	LESS 20% DISCOUNT		-372.03	-217.53
			1,488.12	870.12
<u>NETT ITEMS</u>				
1	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	NO PLATE (S) W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
<u>LABOUR</u>				
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
	TOWING FEE. (NPA)		-	-
			720.00	550.00
GRAND TOTAL			2,419.62	1,631.62
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,631.62

Report Ref No. NS/INC20005066/T1yf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.