

ASS. REC. BY: Tough

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 3HC2454AYr Regn: 2019, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundaic.c. 1580Colour: Blue

U/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHG851CVK164587Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Davent

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 6/4/20Survey held at Comfort byersDes. of Damages: Frt 6 Rear 6 / S / N / S / U / C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

by the week

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. _____

Photos _____

Others _____

Rep. Form: _____

Lump Sum / B.B. (\$ _____)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC - CP/P)
LKK -

Date: 06.04.2020

Time: 14:59:59

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO : 305392292
REGN NO : SHC2454A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 05.04.2020 13:10
ACCIDENT DATE : 05.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	de
0002	04-01-0104-2288-G	REAR BUMPER BEAM	1	294.80	20.00	235.84	?
0003	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	cm
0004	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	de
0005	04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	x
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	re
0007	09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00	nw
0008	FNPS	NO PLATE(S)W/TRIM COVER	1 N	55.00	10.00	49.50	wa
0009	04-01-0104-3819-G	REAR BUMPER BEAM STAY LH	1	138.10	20.00	110.48	?
0010	04-01-0104-3919-G	REAR BUMPER BEAM STAY RH	1	138.10	20.00	110.48	?

SUB-TOTAL : 1,699.62

JOB NATURE

0000 PB

PANEL BEATING

350.00

320.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 06.04.2020
Time: 14:59:59
Page: 2/2

NTUC-CP/P/
LKK -

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305392292
REGN NO : SHC2454A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 05.04.2020 13:1
ACCIDENT DATE : 05.04.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 SP	SPRAYPAINT CHARGE	250.00		200.		
0002 L	R/I REVERSE SENSOR	120.00		30.		
0003 23-01	TOWING FEE	0.00				
SUB-TOTAL :						720.00

TOTAL : 2,419.62

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tan Jia 97495749
WP
6/4/20 02 days
p/p Resurvey before paint
Tan Jia C / Khantoon
Sur C / Khantoon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Need Taxi Replacement
Yes / No

Janet Lim

COMFORTDELGRO
ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Singapore Road Singapore 119117
Mainline : 65 4781 1980 Facsimile : 65 4780 9750

Workshops

191 Serangoon Drive Singapore 550899 24 Serangoon Loop Singapore 758158
360 Serangoon Drive Singapore 555711 27 Sungei Road Singapore 728791
160 Serangoon Road Singapore 556449 100 Serangoon Road Singapore 556449

Date/Time: 06.04.2020 14:48 Page: 1

Team: ARC Repair TP (CLSO)

JOB CARD

Sales Order:

305392292

JC NO.

COMFORT TRANSPORTATION PTE LTD
38.3 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO	SHC2454A	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	IONIQ (G2)	DATE/TIME IN
YR OF MANU	10.07.2019	TARGET DATE
CHASSIS CODE	KMH0851CVKU164587	COMPLETION DATE/TIME

COUNT CARD NO

Accident Date: 05.04.2020
NATURE: 3P 05.04.2020


✓ TOW

JOB DESCRIPTION

PP
NTUC - SBR
989D

LKK-

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

SHC2454A

LIMITS

Exit Pass

Vehicle No.: SHC2454A

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

Service Advisor

Service Reception upon collection