

NS/INC20005067/T1qf3

REF:

INC

ASS. REC. BY:

Taufikh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No 5113699456 (02/11/19-01/11/2020)

Claims No. MT/1090718-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SHA94521

Yr Reg:

2016, Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c 1685

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

459153

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHL154144 6.4092602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil AS/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

C

mm

R/Bal.

C

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/4/20

Survey held at

Compete Loging

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/04/20 @ 10.51am Taufikh finalised with Larry LS \$1100, 2 days.

(Red \$2538.50, 70%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 14/04 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

S - PS - SI

Photos

Others

Rep. Format: TP

LS \$1100

REPAIR ESTIMATE*

VEHICLE NO : SHA9452U

DATE: 4. Apr. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 3. Apr. 2020

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper			del \$553.00
10	Rear Bumper Clips		\$2.20	wa \$22.00
1	Rear Bumper Sponge			? \$103.50
1	Rear Bumper Reinforcement			? \$428.40
2	Rear Bumper Reinforcement Brackets LH/RH		\$80.30	? \$160.60
1	Rear Bumper Undercover			del \$228.00
1	Rear Panel			x \$592.30
1	Rear panel Garnish			x \$57.70
1	Rear panel Lower Garnish			x \$495.50
SUB TOTAL				\$2,641.00
LESS 20%				\$528.20
DISCOUNTED TOTAL				\$2,112.80
1	Rear Bumper Rubber Mat			wa \$50.00
1	Reverse Sensor			wa \$135.70
				Nett
				Nett
				\$185.70
Labour Charge				
1	Panel Beating			280 \$600.00
1	Spray Painting Charge			200 \$500.00
1	Tuff Kote			x \$80.00
1	Wiring Charge			30 \$60.00
1	Remove/refix Reverse Sensor			30 \$100.00
TOTAL LABOUR				\$1,340.00
ESTIMATE TOTAL				\$3,638.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Larry Ng

Tanjin 97495749

wp
6/4/20

Wingsun
Resurvey after repair
02 days

tanjin@lkkauto.com
sure@lkkauto.com

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579 001
Mainline + 65 6383 8280 Facsimile + 65 6280 9755

Workshops

54 Luyang Drive Singapore 530009
383 Sin Ming Drive Singapore 575 177
15 Pandan Road Singapore 609286
120 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728735
301 Yishun Industrial Park A Singapore 760001

Date/Time: 04.04.2020 09:39

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305392006

STOMER

CITYCAB PTE LTD

/MS

7010070

STOMER NO

383 SIN MING DRIVE

DRESS

Singapore SINGAPORE 575717

65551188

(R)

(O)

(P)

Accident Date: 03.04.2020

NATURE: 3P 03.04.2020

JOB DESCRIPTION

S/NO


LABOR CODE

DESCRIPTION

NTUC - Rear

LKR

REGN NO	SHA9452U	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	E..... 1/2.....
YR OF MA	11.08.2016	DATE/TIME IN
CHASSIS CODE	KMHLB410M9U092602	TARGET DATE
		COMPLETION DATE/TIME



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

SHA9452U

LARRY

Exit Pass

SHA9452U

Vehicle No.:

Larry Ng

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

405-460000