THE LTD

* ESTIMATE*

: SHA9452U CLE NO

: HYUNDAI

4. Apr. 2020 DATE:

MODEL : i40

Qty Parts Description/ Labour Type Unit Price Amount 1 Rear Bumper 10 Rear Bumper Clips \$2.20	0
10 Rear Bumper Clips \$2.20 \$22.0	0
10 Rear Bumper Clips \$2.20 \(\sigma	- 1
	0
1 Rear Bumper Sponge	
1 Rear Bumper Reinforcement $\stackrel{\text{in}}{\searrow} 3$ \$428.4	0
Rear Bumper Reinforcement Brackets LH/RH \$80.30 \$160.6	
1 Rear Bumper Undercover	0
1 Rear Panel X ^^ \$592.3	0
1 Rear panel Garnish	0
1 Rear panel Lower Garnish ↑↑ ★ \$495.5	0
SUB TOTAL 803 \$2,641.0	0
LESS 20% \$528.2	
DISCOUNTED TOTAL 642.40 \$2,112.8	0
	i
1 Rear Bumper Rubber Mat \$50.0	0 Nett
1 Reverse Sensor \$135.7	0 Nett
LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	
 To display damaged part(s) during resurvey 	
Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	
No illegal modification(s) is allowed	0/
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	_
1 Panel Beating Acknowledged by Repairer 280 \$600.0	00
1 Spray Painting Charge Signature: 200 \$500.0	00
1 Tuff Kote Date: nn x \$80.0	
1 Wiring Charge \$60.0	00
1 Remove/refix Reverse Sensor \$100.0	
\$100.0	,
TOTAL LABOUR 540 \$1.340.0	_
\$1,340.6	00
ESTIMATE TOTAL	_
ESTIMATE TOTAL \$3,638.	0
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will	
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.	

raun va

Taufin 97495749

6/4/20

Lungson

Resurry after aports

02 days

taufin e Milantown

eur Chhantown

642.40 1368.10 1368.10 4/sd 1100 ** 02days 185.70