

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Reg. No: 52983356E GST Reg. No. 20-0405911-H

#### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No.

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

**INV** Date

Reference

27/04/2020

NA2002749

NS/INC20005070/T1qf3n2

Code



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 6336L

Insured Veh. SMS 1048C

Claim No. MT/1090831-002

Policy No.

Accident Date 04/04/2020

Inspection Date 06/04/2020

| Description         | Total  |
|---------------------|--------|
| Survey Inspection   | 160.00 |
| Resurvey Inspection |        |
| Digital Photographs |        |
| Transportation      |        |
| Subtotal            | 160.00 |
| GST (7%)            | 11.20  |
| Grand Total         | 171.20 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

**National Assessment Centre Services** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







| NTUC INCOME INSURANCE CO-OPERATIVE LTD |  | Ref:  | NS/INC20005070/T1qf3n2 |                          |            |  |  |  |  |
|--|--|---|------------------------|--------------------------|------------|--|--|--|--|
|  |  | D<br>UNION HOUSESINGAPORE                               | Date:                  | 27-04-2020<br>INC4       |            |  |  |  |  |
| 1.                                     | 1. Policy Particulars :- THIRD PARTY CLAIM |   |                        |                          |            |  |  |  |  |
|  | Insured Veh.                               | SMS 1048C   | Veh. Ir                | Veh. Inspected SHB 6336L |            |  |  |  |  |
|  | Policy No.                                 |   | Cover                  | age (\$)                 | 0.00       |  |  |  |  |
|  | Claim No.                                  | MT/1090831-002  | Exces                  | s (\$)                   | 0.00       |  |  |  |  |
|  | Assign From                                |   | Assign Date            |                          | 06/04/2020 |  |  |  |  |
| 2.                                     |  | Vehicle Partic  | culars 8               | Condition                |            |  |  |  |  |
|  | Make & Model                               | HYUNDAI IONIQ   | c.c                    |                          | 1580       |  |  |  |  |
|  | Engine No.                                 | HIDDEN  | Year o                 | f Reg.                   | 2019       |  |  |  |  |
|  | Chassis No.                                | KMHC851CVKU145951                                       | Colou                  | r                        | BLUE       |  |  |  |  |
|  | Odometer                                   | -   | Steering               |                          | IN ORDER   |  |  |  |  |
|  | Brakes                                     | IN ORDER  | Modification           |                          | SPORTS RIM |  |  |  |  |
|  | General                                    | GOOD  |                        |                          |            |  |  |  |  |
| 3.                                     |  | Conditi   | ons of                 | Tyres                    |            |  |  |  |  |
|  |  | Size  | Make                   |                          | Balance    |  |  |  |  |
|  | R/H Front Tyre                             | 195/65 R15  | WEST                   | LAKE                     | 6 mm       |  |  |  |  |
|  | L/H Front Tyre                             | 195/65 R15  | WEST                   |                          | 6 mm       |  |  |  |  |
|  | R/H Rear Tyre                              | 195/65 R15  | WEST                   |                          | 6 mm       |  |  |  |  |
|  | L/H Rear Tyre                              | 195/65 R15  | WEST                   |                          | 6 mm       |  |  |  |  |
| 4.                                     |  | Description   |                        | -                        |            |  |  |  |  |
|  | THE VEHICLE SU                             | STAINED DAMAGES AT THE REA                              | AR POR                 | TION.                    |            |  |  |  |  |
|  | DAMAGES SEE D                              | ETAILS.   |                        |                          |            |  |  |  |  |
| 5.                                     |  | Genera  | Inform                 | ation                    |            |  |  |  |  |
|  | Accident Date                              | 04/04/2020  | Inspec                 | tion Date                | 06/04/2020 |  |  |  |  |
|  | Survey held at                             | Survey held at COMFORTDELGRO ENGINEERING PTE LTD        |                        |                          |            |  |  |  |  |
|  |  | 59 LOYANG DRIVE<br>SINGAPORE 508969                     |                        |                          |            |  |  |  |  |
| 5a.                                    |  | Re  | emarks                 |                          |            |  |  |  |  |
|  |  | ON WAS CONDUCTED ON A"WIT<br>CE TO YOUR INSTRUCTIONS, W |                        |                          |            |  |  |  |  |
| 5b.                                    | 5b. Estimate Days of Repair                |   |                        |                          |            |  |  |  |  |
|  | ESTIMATED NORI                             | MAL PERIOD FOR REPAIR:                                  |                        | 2 Working Days           |            |  |  |  |  |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6336L

| Qty | Description of Parts                                      | Condition               | Estimate By Workshop (\$) | Our Adjusted<br>(\$) |
|-----|---|-------------------------|---------------------------|----------------------|
|     | REPLACEMENT OF PARTS                                      |                         |                           |                      |
| 1   | COVER-RR BUMPER   | TO REPAIR SEE<br>LABOUR | 459.40                    | -                    |
| 1   | MOULDING-RR BUMPER CTR                                    | DEFORMED                | 451.25                    | 451.25               |
| 1   | LAMP ASSY-REAR FOG  | NOT NECESSARY           | 201.50                    | -                    |
| 10  | BUMPER COVER CLIP REAR                                    | NECESSARY               | 22.00                     | 22.00                |
|     | LESS 20% DISCOUNT   |                         | -226.83                   | -94.65               |
|     |   |                         | 907.32                    | 378.60               |
|     | SPECIAL NETT ITEMS  |                         |                           |                      |
| 1   | REVERSE SENSOR ASSY (SN)                                  | NOT WORKING             | 180.00                    | 180.00               |
| 1   | PROTECTOR MAT (SN)  | NECESSARY               | 50.00                     | 50.00                |
| 1   | NO PLATE (S) W/TRIM COVER (SN)                            | CRACKED                 | 55.00                     | 55.00                |
|     |   |                         | 285.00                    | 285.00               |
|     | <u>LABOUR</u>   |                         |                           |                      |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER-RR BUMPER. |                         | 350.00                    | 320.00               |
|     | SPRAYPAINT CHARGE.  |                         | 250.00                    | 200.00               |
|     | R/I REVERSE SENSOR.                                       |                         | 120.00                    | 30.00                |
|     |   |                         | 720.00                    | 550.00               |
|     | GRAND TOTAL   |                         | 1,912.32                  | 1,213.60             |

| RECOMMENDED COST OF REPAIRS (CONFIRMED) |  |  | 1,213.60 |
|---|--|--|----------|
|---|--|--|----------|

Report Ref No. NS/INC20005070/T1qf3n2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

### PHOTOGRAPHS FOR VEHICLE NO. SHB 6336L

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

#### PHOTOGRAPHS FOR VEHICLE NO. SHB 6336L

#### RE-INSPECTION







