

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005074/KKA3Q2

Date: 29/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800151649
Claimant		
Vehicle No : SMA7706S	Insured Vehicle No :	SMG4838H
Date of Loss: 05/04/2020	Nature of Claim: TP	Claim No: 8589554126SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7706S	Engine No:	LEB6552652
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71210391
Reg. Date:	19/06/2018 (Man. Year: 2018)	Odometer:	128310 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,408.72	969.68	1,439.04	59.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	1,025.00	565.00	35.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,998.72	1,994.68	2,004.04	50.12
+ GST 7.00/7.00% (S\$)	279.91	139.63	140.28	50.12
Nett Amount (S\$)	4,278.63	2,134.31	2,144.32	50.12
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/04/2020	
Date Inspected:	07/04/2020 Inspected At:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,150.60 FL	*1,150.60 FL
2	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	26.50 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Distorted	26.50 FL	*26.50 FL
5	1		*REAR BUMPER BRACKET LH	Repair	48.70 FL	*- FL
6	1		*REAR BUMPER BRACKET RH	Repair	48.70 FL	*- FL
7	2		*REAR BUMPER SPONGE	Serviceable	179.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Serviceable	45.00 FL	*- FL
9	1		*REAR BUMPER REFLECTOR GARNISH RH	Serviceable	45.00 FL	*- FL
10	1		*RH REAR FENDER	Repair	1,010.90 FL	*- FL
11	1		*RH REAR FENDER UNDERSHIELD	Serviceable	105.00 FL	*- FL
12	10		*RH REAR FENDER UNDERSHIELD CLIP	Not Necessary	40.00 FL	*- FL
13	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,960.90	1,212.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	552.18	242.42
Total Parts (\$\$)	2,408.72	969.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,RHR FENDER)	New	600.00	500.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,RHR FENDER)	New	600.00	440.00
3	TO TUFF COAT	New	100.00	0.00
4	TO CHECK WIRING	New	50.00	15.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
6	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
Gross Labour Cost (\$\$)			1,590.00	1,025.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >