



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006123
INV Date 07/09/2020
Reference CC6/CTI20005077/Uba3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBC 291L
Insured Veh. SJJ 4939U
Claim No. SNM20D201554
Policy No. DMPCSN3059241901
Accident Date 29/03/2020
Inspection Date 08/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20005077/Uba3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJJ 4939U	Veh. Inspected	GBC 291L
Policy No.	DMPCSN3059241901	Coverage (\$)	0.00
Claim No.	SNM20D201554	Excess (\$)	0.00
Assign From		Assign Date	08/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTFAT35Y30K201432	Colour	WHITE
Odometer	393965	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	6 mm
L/H Front Tyre	195 R15	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/03/2020	Inspection Date	08/04/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 291L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	TO REPAIR SEE LABOUR	1,455.10	-
1	TAILGATE TOYOTA STICKER	NECESSARY	275.00	146.20
2	TAILGATE LOCK LATCHS @\$245.00	TO REPAIR SEE LABOUR	490.00	-
2	TAILGATE 'L' LOWER PANELS @\$115.00	O/S BENT	230.00	115.00
2	TAILGATE 'L' LOWER PANEL RUBBERS @\$105.00	O/S TORN	210.00	60.00
1	TAILGATE LOWER MEMBER	BENT	655.10	495.50
2	TAILLAMPS @\$296.90	CRACKED	593.80	593.80
2	TAILLAMP BRACKETS @\$105.00	O/S BENT	210.00	89.20
1	REAR EXHAUST	TO REPAIR SEE LABOUR	488.20	-
1	'DYNA' EMBLEM	NECESSARY	68.00	68.00
1	REAR SPARE TYRE CHAIN & BRACKET	TWISTED / JAMMED	398.20	398.20
1	REAR LICENCE PLATE BRACKET	BENT	198.50	89.20
1	REAR DROPSIDE GATE LOWER MEMBER O/S	TO REPAIR SEE LABOUR	899.20	-
1	FRONT PANEL	DENTED	1,215.10	1,005.10
1	FRONT PANEL CENTRE BLACK GARNISH	NOT NECESSARY	366.50	-
2	FRONT CORNER PANELS @\$205.00	TO REPAIR SEE LABOUR	410.00	-
1	FRONT DYNA STICKER	NECESSARY	85.00	85.00
1	FRONT WINDSCREEN RUBBER	NECESSARY	211.10	211.10
1	FRONT GRILLE	CRACKED	675.10	475.10
1	FRONT GRILLE LOGO	NECESSARY	105.00	65.20
2	HEADLAMPS @\$705.10	CRACKED	1,410.20	1,034.20
1	FRONT BUMPER	BENT	488.20	394.10
1	FRONT CROSS MEMBER	BENT	655.50	485.50
1	FRONT CABIN CROSS MEMBER	NOT NECESSARY	850.10	-
1	AIR CON BLOWER	CRACKED	1,005.30	875.10
1	AIR CON HEATER UNIT	NOT NECESSARY	1,650.00	-

Report Ref No. CC6/CTI20005077/Uba3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-1,671.38
			15,298.20	5,014.12
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
1	SET 13 PAX & 70KM/H STICKER (SN)	NECESSARY	30.00	20.00
1	REAR STEP PANEL (SN)	BENT	180.00	180.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	TAILGATE ALUMINIUM PLATE (SN)	NOT NECESSARY	680.00	-
1	FRONT LICENCE PLATE (SN)	BENT	20.00	14.00
			1,210.00	428.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	80.00	-
	TO REFILL AIR CON GAS.		100.00	100.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN .		150.00	60.00
	TO DISMANTLE & REFIX FRONT DASHBOARD .		300.00	160.00
	TO DISMANTLE & REPLACING AIR CON BLOWER.		100.00	80.00
	TO SPRAY RUST PROOFING .		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE, TAILGATE LOCK LATCHS, REAR EXHAUST ,REAR DROPSIDE GATE LOWER MEMBER O/S AND FRONT CORNER PANELS .		1,800.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,200.00
			4,760.00	2,940.00
GRAND TOTAL			21,268.20	8,382.12

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,700.00
---	--	--	-----------------

Report Ref No. CC6/CTI20005077/Uba3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.