

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20005078/GQF3E2

Date: 15/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLC5792G

Insured Vehicle No : SHD3135J

Date of Loss: 07/04/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC5792G	Engine No:	2ZR0413904
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE200001461
Reg. Date:	15/09/2009 (Man. Year: 2009)	Odometer:	249866 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	CST 5 mm	Rear Left Side:	CST 5 mm
Front Right Side:	CST 5 mm	Rear Right Side:	CST 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,578.40	659.90	3,918.50	85.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,100.00	1,400.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,078.40	1,759.90	5,318.50	75.14
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	7,078.40	1,400.00	5,678.40	80.22

INSPECTION

Date of Assignment: 08/04/2020
Date Inspected: 08/04/2020 Inspected At:

T & S MOTOR SERVICE (HQ)
BLK 5035 ANG MO KIO INDUSTRIAL
PARK 2 #01-357
SINGAPORE 569538

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2020)
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC5792G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,272.40 F	*- FL
2	1		*TAILGATE GLASS MOULDING	Not Necessary	180.00 F	*- FL
3	1		*TAILGATE LOGO EMBLEM	Necessary	72.90 F	*72.90 FL
4	1		*TAILGATE INNER TRIM	Not Necessary	345.20 F	*- FL
5	1		*TAILGATE LOCK	Not Necessary	470.40 F	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	322.30 F	*- FL
7	1		*REAR BUMPER	Deformed	500.30 F	*500.30 FL
8	2		*REAR BUMPER REFLECTOR	Not Necessary	115.20 F	*- FL
9	2		*REAR BUMPER SIDE RETAINER LH & RH	Not Necessary	121.60 F	*- FL
10	2		*REAR BUMPER IMPACT BRACKET LH & RH	Not Necessary	179.60 F	*- FL
11	1		*REAR END PANEL	Repair	468.50 F	*- FL
12	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 F	*- FL
13	1		*TAILGATE GLASS INNER SEAL	Not Necessary	40.00 F	*- FL
14	1		*PANEL JOINT SEALANT	Not Necessary	60.00 F	*- FL
15	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	60.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
17	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,578.40	803.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	143.30
Total Parts (\$\$)	4,578.40	659.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT REAR TRIMMINGS, ETC	New	150.00	60.00
2	LABOUR TO REPLACE & REFIT REVERSE SENSOR	New	100.00	40.00
3	LABOUR TO REPLACE & REFIT TAILGATE GLASS	New	200.00	0.00
4	SPRAY PAINTING ON ACCIDENT AFFECTED AREAS	New	900.00	600.00
5	TO APPLY RUSTPROOF TREATMENT TO THE REPLACED / REPAIRED PARTS	New	150.00	0.00
6	TO CONDUCT WIRING CHECK	New	100.00	0.00
7	LABOUR CHARGE FOR REMOVE, REPLACE AND REFIT ACCIDENT DENTED PARTS AND PANEL BEAT ACCIDENT DENTED PARTS	New	900.00	400.00
			Gross Labour Cost (S\$)	2,500.00
				1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >