Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005080/KBA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900114145 Policy No: Claimant SKQ5601M Insured Vehicle No: SGA3332J Vehicle No:

Date of Loss: 05/04/2020 Nature of Claim: ΤP Claim No: 4727803090SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKQ5601M Reg No:

Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1480318

Reg. Date: 10/12/2014 (Man. Year: 2014) Chassis No: JTDGG20WX0J001919

Colour: Metallic Gold Odometer: 117660 km

Engine Capacity: 1798 cc

Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm Front Right Side: Rear Right Side: Yokohama 8 mm Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,781.73	2,817.96	1,963.77	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,800.00	970.00	35.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,551.73	4,617.96	2,933.77	38.85
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	7,551.73	3,700.00	3,851.73	51.00
+ Car Rental (8.0 x S\$1	+ Car Rental (8.0 x S\$120.00/day) (S\$)			
Nett Liability (S\$)		4,660.00		

INSPECTION

07/04/2020 Date of Assignment:

Date Inspected: 07/04/2020 Inspected At: Eng Heng Automobil Trading Co (HQ)

Global Sum Settlement (S\$)

Blk 10 #01-01 Ang Mo Kio Part 2A

AutoPoint

4,600.00

Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Bent / Cracked	470.39 F	*470.39 FL	
2	1		*REAR BUMPER HOLDER -LEFT	Distorted	41.65 F	*41.65 FL	
3	1		*REAR BUMPER HOLDER -RIGHT	Distorted	41.65 F	*41.65 FL	
4	1		*REAR BUMPER BRACKET	N/S Bent	96.88 F	*48.44 FL	
5	10		*REAR BUMPER CLIPS	Necessary	36.00 F	*36.00 FL	
6	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
7	1		*REAR BOOT COVER	Bent	1,209.65 F	*1,209.65 FL	
8	1		*REAR BOOT RUBBER (50%)	Cut	303.79 FS	*151.89 FS	
9	1		*REAR BOOT COVER LOCK -UPPER	Dented	443.50 F	*443.50 FL	
10	1		*REAR BOOT COVER LOCK -LOWER	Repair	34.86 F	*- FL	
11	1		*REAR END PANEL	Bent	440.85 F	*440.85 FL	
12	1		*REAR END PANEL GARNISH	Buckled	232.96 F	*232.96 FL	
13	1		*REAR SILENCER	Repair	826.55 F	*- FL	
14	1		*SET REAR WINDSCREEN RUBBER	Necessary	180.00 F	*180.00 FL	
15	1		*ELEGANCE BADGE	Necessary	55.00 F	*55.00 FL	
16	1		*VALVE MATIC BADGE	Necessary	88.00 F	*88.00 FL	
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	-			
				Sub Total (S\$)	4,781.73	3,639.98	
	- List Item Discount on L Items 0.00/25.00% (S\$) 0.00 822.02					822.02	
				Total Parts (S\$)	4,781.73	2,817.96	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	PANEL BEATING ,JACK AND STRAIGHTEN REAR SPARE TYRE COMPARTMENT ,REPLACE ,OR REPAIR & WELD NECESSARY PARTS	New	1,200.00	800.00					
2	PAINT REPLACEMENT PARTS AND REPAIR DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE	New	1,200.00	800.00					
3	DISMANTLE N REFIX REAR W/SCREEN GLASS	New	220.00	120.00					
4	TO DISMANTLE AND REFIT REAR BOOT LID ACCESSORIES ,WIPER MOTOR CHECK AND TEST ELECTRICAL CIRCUIT	New	150.00	80.00					
	Gross Labour Cost (S\$)		2,770.00	1,800.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >