

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005084/UGA3Q2

Date: 16/02/2021

### REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 2070005876   |
| Claimant Vehicle No : | SJF9626K                             | Insured Vehicle No : | SMS184Z      |
| Date of Loss:         | 08/04/2020                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 8708031491SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJF9626K                     |             |                   |
| Make & Model:               | TOYOTA VIOS EA, 1.5 (A)      | Engine No:  | 1NZX754965        |
| Reg. Date:                  | 17/06/2008 (Man. Year: 2008) | Chassis No: | MR053HY9305065641 |
| Colour:                     | Black                        | Odometer:   | 202267 km         |
| Engine Capacity:            | 1497 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 205/45 R16       | Rear Tyre Size:  | 205/45 R16       |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                           | 7,399.50         | 2,743.82        | 4,655.68        | 62.92        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00            |              |
| Labour                                          | 2,910.00         | 1,310.00        | 1,600.00        | 54.98        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00            |              |
| Towing                                          | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>10,309.50</b> | <b>4,053.82</b> | <b>6,255.68</b> | <b>60.68</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>3,200.00</b> |                 |              |
| <b>(S\$)</b>                                    | 10,309.50        | 3,200.00        | 7,109.50        | 68.96        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 721.67           | 224.00          | 497.67          | 68.96        |
| <b>Nett Amount (S\$)</b>                        | <b>11,031.17</b> | <b>3,424.00</b> | <b>7,607.17</b> | <b>68.96</b> |
| <b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b> |                  | 200.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>3,626.00</b> |                 |              |

### INSPECTION

|                             |            |                                                                                                         |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 08/04/2020 |                                                                                                         |
| Date Inspected:             | 08/04/2020 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 4.0 days   |                                                                                                         |

---

**Adjuster:** MARCUS CHUA**Manager:** KENNETH KONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition           | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------------|---------------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER                           | Deformed / Torn     | 688.20 F   | *420.11 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER N/S         | Bent / Cracked      | 66.50 F    | *63.15 FL  |
| 3   | 1   |          | *FRONT BUMPER FOG LAMP N/S              | Not Necessary       | 315.20 F   | *- FL      |
| 4   | 1   |          | *FRONT FENDER N/S                       | Dented / Bent       | 588.10 F   | *388.50 FL |
| 5   | 1   |          | *FRONT FENDER INNERSHIELD N/S           | Torn                | 199.20 F   | *199.20 FL |
| 6   | 1   |          | *SET FRONT FENDER INNERSHIELD CLIPS N/S | Necessary           | 50.00 F    | *50.00 FL  |
| 7   | 1   |          | *FRONT FENDER VVTI EMBLEM N/S           | Necessary           | 78.50 F    | *78.50 FL  |
| 8   | 1   |          | *FRONT SHOCK ABSORBER N/S               | Not Necessary       | 399.20 F   | *- FL      |
| 9   | 1   |          | *FRONT LOWER ARM N/S                    | Not Necessary       | 419.20 F   | *- FL      |
| 10  | 1   |          | *FRONT DOOR N/S                         | Repair              | 1,099.20 F | *- FL      |
| 11  | 1   |          | *HEADLAMP N/S                           | Scratched / Cracked | 866.20 F   | *512.30 FL |
| 12  | 1   |          | *FRONT BUMPER LOWER SKIRTING            | Deformed / Torn     | 880.00 FS  | *680.00 FS |
| 13  | 1   |          | *SET FRONT BUMPER CLIPS                 | Necessary           | 50.00 FS   | *50.00 FS  |
| 14  | 1   |          | *FRONT SPORT RIM N/S                    | Repair              | 800.00 FS  | *- FS      |
| 15  | 1   |          | *ROCKER PANEL GARNISH N/S               | Deformed / Torn     | 850.00 FS  | *680.00 FS |
| 16  | 1   |          | *FRONT FENDER LOCK CATCH N/S            | Damaged             | 50.00 FS   | *50.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>7,399.50</b> | <b>3,171.76</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (S\$)</b> | <b>0.00</b>     | <b>427.94</b>   |
| <b>Total Parts (S\$)</b>                                 | <b>7,399.50</b> | <b>2,743.82</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                       | Particulars                                | Lab.Type | Repairer's | Amount   |
|--------------------------|--------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>      |                                            |          |            |          |
| 1                        | TO CHECK WIRING                            | New      | 50.00      | 20.00    |
| 2                        | TO SPRAY RUST PROOFING                     | New      | 80.00      | 30.00    |
| 3                        | TO CONDUCT WHEEL ALIGNMENT                 | New      | 120.00     | 60.00    |
| 4                        | TO DISMANTLE & REFIX FRONT UNDERCARRIAGE   | New      | 180.00     | 0.00     |
| 5                        | TO TRANSFER FRONT DOOR MECHANISM           | New      | 100.00     | 0.00     |
| 6                        | LABOUR FOR PANEL BEATING & REPLACING PARTS | New      | 880.00     | 400.00   |
| 7                        | TO PUTTY & SPRAY PAINTING                  | New      | 1,500.00   | 800.00   |
| Gross Labour Cost (\$\$) |                                            |          | 2,910.00   | 1,310.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >