

ASS. REC. BY:

erl.

05/10/2000 5086/64 f3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Tan Lim

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$58K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GRJ3817P

Yr Regn:

05 Apr 2019

Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna 1500cc 2982

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFA735YXOK212539

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In Order / Jammed / Leaked / Burnt or

Brake: ☒ In Order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/75 R15

R:

155 RR

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

08-04-20

Survey held at

w/s

4pm

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

06:24290

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

Report Form:

Policy No : DHOM110167731901

Date of Accident : 06 April 2020



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department

United Overseas Insurance Ltd

3 Anson Road #28-01

Springleaf Tower

Singapore 079909

Date : 07 April 2020

Estimate To Repair GBJ3817P - Toyota DYNA 100 MANUAL

Chassis No : JTFAT35YX0K212539

Rep: Uk - Guo qian
08/04/2020 C1610/hn

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front windscreen glass / sm	\$ 1,541.00
02	1 pc	front windscreen glass weatherstrip / mc	\$ 308.00
03	1 pc	front body panel / P.S.	\$ 310.00
04	2 ps	front body side apron garnish @ \$130.00 / re	\$ 260.00
05	1 pc	wiper centre panel / P.S.	\$ 275.00
06	2 ps	wiper panel nozzle @ \$47.00 / mis	\$ 94.00
07	2 ps	wiper panel nozzle lock nut @ \$21.00 / mis	\$ 42.00
08	1 pc	wiper linkage / sm	\$ 365.00
09	1 pc	wiper motor / NW	\$ 627.00
10	2 ps	wiper arm @ \$122.00 / cut / mis	\$ 244.00
11	2 ps	wiper arm lock mute cover @ \$35.00	\$ 70.00
12	2 ps	wiper blade @ \$85.00 / cut	\$ 170.00
13	1 pc	front centre grille emblem badge / mc	\$ 75.00
14	1 pc	front Dyna emblem / mc	\$ 85.00
15	1 pc	front bumper / cut	\$ 700.00
16	2 ps	headlamps @ \$842.00 / CRA	\$ 1,684.00
17	2 ps	headlamp lower finisher @ \$30.00 / CRA	\$ 60.00
18	2 ps	front bumper stay @ \$255.00 ?	\$ 510.00
19	2 ps	front bumper fog lamp garnish @ \$140.00 X NN	\$ 280.00
20	2 ps	front wing mirror assy @ \$685.00 < LH X NN RH - BT.	\$ 1,370.00
21	1 pc	o/s front door / P.S.	\$ 1,600.00
22	1 pc	o/s front door hinges / BT	\$ 95.00
23	1 pc	o/s front door checker/arrestor / BT	\$ 150.00
24	1 pc	o/s front door inner lock / BT	\$ 286.00
25	1 pc	o/s front door inner lock striker X NN	\$ 31.00
26	1 pc	o/s front door window glass / P.S.	\$ 725.00
27	1 pc	o/s front door window glass channel weatherstrip / re	\$ 220.00
28	1 pc	o/s front door outer weatherstrip moulding / re	\$ 103.00
29	1 pc	o/s front door inner trimboard / re	\$ 565.00
30	1 pc	o/s front door 1/4 garnish outer / re	\$ 46.00
31	1 pc	o/s front door power window motor X NW	\$ 553.00
32	1 pc	o/s front door regulator	\$ 375.00
33	1 pc	o/s front door weatherstrip / Twi	\$ 195.00
34	1 pc	o/s front door step garnish X	\$ 300.00
35	1 pc	o/s front door kicking plate X	\$ 195.00
36	2 ps	dashboard speaker @ \$235.00 X	\$ 470.00
37	1 pc	o/s front door channel weatherstrip X	\$ 220.00

Date of Accident : 06 April 2020

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
United Overseas Insurance Ltd
3 Anson Road #28-01
Springleaf Tower
Singapore 079909

Date : 07 April 2020

Estimate To Repair GBJ3817P - Toyota DYNA 100 MANUAL

Chassis No : JTFAT35YX0K212539

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
38	1 pc	instrument dashboard finisher centre /	\$ 389.60
39	1 pc	instrument dashboard assy /	\$ 1,050.00
40	1 pc	instrument dashboard lower cover left /	\$ 189.60
41	1 pc	instrument dashboard lower cover centre /	\$ 269.80
42	1 pc	instrument dashboard reinforcement / BT	\$ 635.00
43	1 pc	instrument glove box assy /	\$ 285.00
44	1 pc	instrument dashboard cluster finisher ?	\$ 235.00
45	1 pc	instrument centre radio cluster facia ?	\$ 482.00
46	1 pc	speedo meter assy ?	\$ 850.00
47	1 pc	steering wheel ?	\$ 985.00
48	1 pc	steering wheel air bag / Act	\$ 700.00
49	1 pc	n/s passenger's seat air bag / Act	\$ 700.00
50	1 pc	steering coupling ?	\$ 725.00
51	1 pc	steering coupling shaft ?	\$ 315.00
52	1 pc	air bag sensor /	\$ 356.00
53	1 pc	air bag module /	\$ 415.00
54	1 pc	air bag spirit sensor /	\$ 238.00
55	2 ps	seat belt and right @ \$875.00 /	\$ 1,750.00
56	2 ps	seat belt buckle and right @ \$124.00 ?	\$ 248.00
57	1 pc	steering column cover top /	\$ 67.00
58	1 pc	steering column cover bottom /	\$ 62.00
59	1 pc	aircon evaporator /	\$ 1,049.00
60	1 pc	aircon blower /	\$ 977.00
61	1 pc	front cabin aircon filter /	\$ 45.00
62	1 pc	heater unit ?	\$ 468.60
63	1 pc	n/s engine mount ?	\$ 135.00
64	1 pc	o/s engine mount ?	\$ 135.00
65	1 pc	gearbox mount ?	\$ 125.00
66	1 pc	air duct heater to register n/s ?	\$ 95.00
67	1 pc	air duct heater to register o/s ?	\$ 95.00
68	1 pc	air duct heater to register centre ?	\$ 95.00
69	2 ps	horn @ \$115.00 ?	\$ 230.00
70	1 pc	heater inlet hose left ?	\$ 95.00
71	1 pc	heater inlet hose right ?	\$ 105.00
72	1 pc	front cross-member sub assy frame ?	\$ 190.00
73	2 ps	front cross-member reinforcement sub-assy inner channel @ \$202.60 ?	\$ 405.20
74	1 pc	front cab sub assy ?	\$ 720.00

Policy No : DHOM110167731901

Date of Accident : 06 April 2020



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
United Overseas Insurance Ltd
3 Anson Road #28-01
Springleaf Tower
Singapore 079909

Date : 07 April 2020

Estimate To Repair GBJ3817P - Toyota DYNA 100 MANUAL

Chassis No : JTFAT35YX0K212539

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
75	1 pc	tiit cab sub front mounting n/s ?	\$ 456.00
76	1 pc	tiit cab sub front mounting o/s ?	\$ 456.00
77	1 pc	front pillar n/s x repair	\$ 370.00
78	1 pc	front pillar garnish n/s	\$ 125.00
79	1 pc	front pillar o/s / Bue	\$ 370.00
80	1 pc	front pillar garnish o/s / n/s	\$ 125.00
81	1 pc	aircon fan assy ?	\$ 1,300.00
82	1 pc	aircon receiver	\$ 88.00
83	1 pc	n/s front door inner trim board x NN	\$ 225.00
84	1 pc	aircon receiver bracket ?	\$ 35.00
85	1 pc	brake fluid resonator tank ?	\$ 856.00
86	1 pc	accelerator pedal ?	\$ 156.00
87	1 pc	accelerator pedal bracket ?	\$ 45.00
88	1 pc	brake pedal ?	\$ 156.00
89	1 pc	brake pedal bracket ?	\$ 45.00
90	1 pc	clutch pedel ?	\$ 156.00
91	1 pc	clutch pedel bracket ?	\$ 45.00
92	1 pc	brake booster ?	\$ 1,685.00
93	1 pc	clutch pump ?	\$ 350.00
94	1 pc	accelerator pedal control unit ?	\$ 358.00
95	1 pc	wiper tank ?	\$ 258.00
96	1 pc	fusebox assy ?	\$ 998.00
97	1 pc	rear cabin glass - front / CPA	\$ 558.00
98	1 pc	front cabin rear grille - left ?	\$ 85.00
99	1 pc	front cabin rear grille - right ?	\$ 85.00
			\$ 40,496.80
Less 25 %			\$ 10,124.20
			\$ 30,372.60
<u>LABOUR & MISC. CHARGES</u>			
01		Towing with king dolly charges. - Invoice	\$ 120.00 ?
02		To check electrical lighting concerned.	\$ 120.00 30
03		To remove and refit front windscreen glass.	\$ 120.00 100
04		To resupply I.U. bracket.	\$ 26.00 /
05		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 320.00 200
06		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 280.00 ?

Policy No : DHOM110167731901

Date of Accident : 06 April 2020



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department

United Overseas Insurance Ltd

3 Anson Road #28-01

Springleaf Tower

Singapore 079909

Date : 07 April 2020

Estimate To Repair GBJ3817P - Toyota DYNA 100 MANUAL

Chassis No : JTFAT35YX0K212539

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 200.00
08		To transfer of door fittings and perform water seepage test.	\$ 120.00
09		To remove and renew SRS airbag sensor, control module, impact sensor and spiral sensor.	\$ 400.00
10		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 300.00
11		Labour re-connect wiring and fusebox	\$ 60.00
12		Labour to bleed brake system.	\$ 150.00
13		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,800.00
14		Putty and spray painting of the affected portion.	\$ 1,600.00
			\$ 6,616.00
		Total	\$ 36,988.60

Excess \$500

Not Authorised.

Guo Qiang
82880282

Impsion repair.

After repair photos.

08/4/2020.

10 Days.

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: