

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20005090/DTF3E2
Date: 04/06/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713
Claimant Vehicle No :	SH8061D	Insured Vehicle No :	SLN6104D
Date of Loss:	06/04/2020	Nature of Claim:	TP Claim No: 622998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8061D		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU614047
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU087924
Colour:	Blue	Odometer:	474402 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,008.52	10,213.24	7,795.28	43.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,670.00	2,260.00	57.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,938.52	11,883.24	10,055.28	45.83
Approved Total (Overridden) (\$\$)		9,500.00		
(\$\$)	21,938.52	9,500.00	12,438.52	56.70
+ GST 7.00/7.00% (\$\$)	1,535.70	665.00	870.70	56.70
Nett Amount (\$\$)	23,474.22	10,165.00	13,309.22	56.70

INSPECTION

Date of Assignment:	08/04/2020	
Date Inspected:	09/04/2020 Inspected At:	BLK 9 SECTOR C #01-42 SIN MING Repairer : Bifrost Auto Pte Ltd (sin Ming) (HQ)
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8061D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Dented	2,174.90 FL	*2,174.90 FL
2	1		*BOOTLID RUBBER	Deformed	96.50 FL	*96.50 FL
3	2		*BOOTLID HINGE (LH/RH)	Not Necessary	569.20 FL	*- FL
4	1		*BOOTLID LOCK UPPER	Serviceable	114.90 FL	*- FL
5	1		*BOOTLID LOCK LOWER	Serviceable	23.20 FL	*- FL
6	1		*BOOTLID I40 EMBLEM (I40)	Not Necessary	67.90 FL	*- FL
7	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	*63.10 FL
8	1		*BOOTLID CRDI PLATE	Not Necessary	52.40 FL	*- FL
9	1		*BOOTLID LAMP (LH/RH) (2PCS)	Cracked/Mtg Cracked(1Pc Only)	2,262.40 FL	*1,131.20 FL
10	1		*BOOTLID TRIMBOARD	Serviceable	343.90 FL	*- FL
11	11		*BOOTLID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
12	1		*BOOTLID MOULDING (I40)	Not Necessary	385.30 FL	*- FL
13	1		*BOOTLID LOWER GARNISH CHROME (I40)	Not Necessary	227.90 FL	*- FL
14	1		*REAR BUMPER	Dented	1,106.00 FL	*553.00 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent / Dented	160.60 FL	*160.60 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
17	1		*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
18	1		*REAR BUMPER SPONGE	Torn	119.50 FL	*119.50 FL
19	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
20	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
21	2		*REAR BUMPER REFLECTOR LAMP (I40)	Not Necessary	64.00 FL	*- FL
22	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,395.60 FL	*1,395.60 FL
23	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	906.00 FL	*- FL
24	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
25	1		*REAR PANEL LOWER	Buckled	367.20 FL	*367.20 FL
26	1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*- FL
27	2		*PANEL ASSY-REAR FLOOR SIDE (LH/RH)	Not Necessary	354.00 FL	*- FL
28	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
29	1		*SPARE WHEEL LOCK NUT	Not Necessary	41.80 FL	*- FL
30	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
31	1		*MEMBER-ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
32	1		*REAR TOWING HOOK	Not Necessary	194.60 FL	*- FL
33	1		*REAR FENDER N/S	Dented	2,171.40 FL	*2,171.40 FL
34	2		*REAR FENDER UNDER SHIELD (LH/RH)	Not Necessary	338.60 FL	*- FL
35	2		*REAR TRAY LUGGS SIDE (LH/RH)	Not Necessary	232.60 FL	*- FL
36	2		*REAR FENDER AIR-DUCT (LH/RH)	Not Necessary	51.60 FL	*- FL
37	2		*REAR FENDER TRIM BOARD (LH/RH)	Not Necessary	688.75 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*EXHAUST PIPE INSULATOR (LH/RH)	Not Necessary	234.20 FL	*- FL
39	1		*EXHAUST SILENCER (LH/RH) (2PCS)	Dented (1Pc Only)	3,870.80 FL	*1,935.40 FL
40	1		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
41	1		*BOOTLID COMFORT LOGO & TEL NO. STICKER	Necessary	16.60 FS	*16.60 FS
42	1		*BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
43	1		*REAR NO PLATE	Not Necessary	25.00 FS	*- FS
44	1		*REAR BUMPER REVERSE SENSOR	Damaged	118.00 FS	*118.00 FS
45	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
46	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	100.00 FS	*100.00 FS
47	1		*SPARE TYRE PANEL CUSHION	Not Necessary	223.10 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,395.75	12,657.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,387.23	2,444.66
Total Parts (\$\$)	18,008.52	10,213.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
7	REMOVE / REFIX FUEL TANK	New	80.00	0.00
8	REMOVE / REFIX EXHAUST PIPE	New	80.00	60.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			3,930.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >