



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 5077R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRAILER END PANEL (SN)	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR TRAILER POWER GATE (SN)	TO REPAIR SEE LABOUR	3,800.00	-
1	REAR TRAILER STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRAILER STICKER 60KM/HR (SN)	NECESSARY	15.00	10.00
1	REAR TRAILER POWER GATE HYDRAULIC PUMP - LH (SN)	DAMAGED / JAMMED	2,800.00	2,100.00
4	LITRE REAR HYDRAULIC OIL (SN)	NECESSARY	320.00	50.00
			8,775.00	2,200.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR TRAILER END PANEL AND REAR TRAILER POWER GATE. }		1,600.00	450.00
	TO REMOVE & REPLACE HYDRAULIC PUMP. }		280.00	-
	TO SPRAY PAINT.		650.00	250.00
			2,530.00	700.00
GRAND TOTAL			11,305.00	2,900.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/AGI20005103/Uyf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.