

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2006883

INV Date 07/10/2020

Reference CC4/FCI20005104/Kga3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKN 4667X

Insured Veh. SHD 4037C

Claim No. D20001829MFSH/1

Policy No. D-20094922MFSH

Accident Date 07/04/2020

Inspection Date 11/04/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS F	S FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20005104/Kga3q2				
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 07-10-2020 Code: FCI2			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHD 4037C	Veh. Inspected	SKN 4667X	
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
	Claim No.	D20001829MFSH/1	Excess (\$)	0.00	
	Assign From	CHRIS	Assign Date	09/04/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA CIVIC (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	JHMFD46209S200774	Colour	METALLIC GREY	
	Odometer	120851	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	GOODYEAR	8 mm	
	L/H Front Tyre	205/55 R16	GOODYEAR	8 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
4.	,	•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.	_	General	Information		
	Accident Date	07/04/2020	Inspection Date	11/04/2020	
	Survey held at	CITY AUTO PTE LTD			
		BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 4667X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LH WHEEL BEARING	NECESSARY	113.40	113.40
1	FRONT LH FENDER	BENT	537.00	537.00
1	FRONT LH FENDER SIGNAL LAMP	CRACKED	18.20	18.20
1	FRONT LH FENDER INNERSHIELD	DISTORTED	104.30	104.30
8	FRONT LH FENDER INNERSHIELD CLIP @\$3.50	NECESSARY	28.00	28.00
1	LH WING MIRROR ASSY	NOT NECESSARY	541.90	-
1	FRONT LH DOOR	BENT	925.20	925.20
2	FRONT LH DOOR HINGE @\$48.60	LOWER BENT	97.20	48.60
1	FRONT LH DOOR CATCHEA	NOT NECESSARY	48.50	-
1	FRONT LH DOOR LOCK	TO REPAIR SEE LABOUR	217.10	-
1	FRONT LH DOOR RUBBER	TORN	104.70	104.70
1	FRONT LH AUDIO SPEAKER	SERVICEABLE	265.00	-
1	FRONT LH DOOR REGULATOR WITH MOTOR	BENT	529.70	529.70
1	FRONT LH DOOR PROTECTOR	DENTED	107.00	107.00
1	FRONT LH DOOR PROTECTOR CHROME	NECESSARY	107.00	107.00
1	REAR LH DOOR PROTECTOR	DENTED	97.10	97.10
1	REAR LH DOOR PROTECTOR CHROME	NECESSARY	97.10	97.10
1	LH ROCKER PANEL	BENT	269.60	269.60
1	REAR LH WHEEL BEARING	NOT NECESSARY	264.60	-
1	FRONT LH DOOR FRAME STICKER	NECESSARY	53.50	53.50
	LESS 20% DISCOUNT		-905.22	-628.08
			3,620.88	2,512.32
	SPECIAL NETT ITEMS			
1	FRONT LH RIM (SN)	DENTED	350.00	280.00
1	REAR LH RIM (SN)	SERVICEABLE	350.00	-
			700.00	280.00
	LABOUR			
	TO CHARGE FRONT LH & REAR LH WHEEL BEARING.		140.00	60.00
	TO CONDUCT WHEEL ALIGNMENT .		75.00	60.00

Report Ref No. CC4/FCI20005104/Kga3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER FRONT LH DOOR COMPONENTS TO NEW DOOR .		80.00	60.00
	TO SPRAY RUBBERIZED UNDER-COATING.		120.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS .INCLUSIVE OF THE REPAIR OF FRONT LH DOOR LOCK .		1,300.00	900.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,400.00	1,100.00
			3,115.00	2,240.00
	GRAND TOTAL		7,435.88	5,032.32

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/FCI20005104/Kga3q2

KONG SENG CHEONG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 4667X

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Sngapore 408933

Reg. No; 199607198R GST Reg. No; 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 4667X


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933





