



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004299/Kpa3q2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-04-2020



ATTN:STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 1320J	Veh. Inspected	SLF 406P
Policy No.	GA047349/1	Coverage (\$)	0.00
Claim No.	S8M0095H	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM42A8G0347337	Colour	METALLIC GREY
Odometer	84446	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	HANKOOK	7 mm
L/H Front Tyre	205/55 R16	HANKOOK	7 mm
R/H Rear Tyre	205/55 R16	HANKOOK	7 mm
L/H Rear Tyre	205/55 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/02/2018	Inspection Date	02/03/2018
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------