

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20005115/R1TF3E2**Date:** 23/07/2020**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00001772010

**Claimant Vehicle
No :** SLW631R**Insured Vehicle
No :** GBB3617S

Date of Loss: 08/04/2020

Nature of Claim: TP

Claim
No: SNM20D201712C02**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLW631R**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 2NRX253358

Reg. Date: 29/01/2018 (Man. Year: 2017)

Chassis No: MR2B23F3X01105010

Colour: Grey

Odometer: 25999 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,511.80	1,896.70	2,615.10	57.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,982.40	4,052.40	3,930.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,494.20	5,949.10	6,545.10	52.39
+ GST 7.00/7.00% (S\$)	874.59	416.44	458.15	52.38
Nett Amount (S\$)	13,368.79	6,365.54	7,003.25	52.39

INSPECTION

Date of Assignment: 09/04/2020

Date Inspected: 10/06/2020 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2020)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW631R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	60.00 FS	*60.00 FS
3	1		*COVER, RR BUMPER L/C	Deformed	526.00 FS	*526.00 FS
4	1		*REINFORCEMENT SUB-AS	Serviceable	332.70 FS	*- FS
5	10		*PIECE, RR BUMPER	Necessary	41.00 FS	*41.00 FS
6	2		*TAPE, MOULDING, NO.1	Necessary	100.80 FS	*100.80 FS
7	1		*RETAINER, RR BUMPER	Serviceable	154.80 FS	*- FS
8	1		*RETAINER, RR BUMPER	Serviceable	154.80 FS	*- FS
9	1		*BACK SENSOR 1D4 SILVER METALLI	Missing	193.90 FS	*193.90 FS
10	1		*ANTENNA, ELECTRICAL	Serviceable	72.00 FS	*- FS
11	2		*ARM SUB-ASSY, RR BUM	Serviceable	137.40 FS	*- FS
12	1		*PANEL SUB-ASSY, BODY	Serviceable	742.30 FS	*- FS
13	1		*PANEL SUB-ASSY, LUGG	Bent	793.20 FS	*793.20 FS
14	1		*LOCK ASSY, LUGGAGE C	Serviceable	399.50 FS	*- FS
15	1		*REAR BOOT LID EMBLEM	Necessary	50.70 FS	*50.70 FS
16	1		*PLATE, LUGGAGE COMPT	Necessary	45.60 FS	*45.60 FS
17	1		*PLATE, LUGGAGE COMPT	Necessary	35.50 FS	*35.50 FS
18	1		*LAMP ASSY, RR RH	Serviceable	245.80 FS	*- FS
19	1		*LAMP ASSY, RR LH	Serviceable	245.80 FS	*- FS
20	1		*REAR REGN PLATE (PO#)	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,511.80** **1,896.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING, LIGHTINGS AND CARRY OUT WATER LEAK TEST	New	122.40	122.40
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	TO REMOVE AND TRANSFER REAR BOOT LID COMPONENT AND MECHANISM TO NEW BOOT LID	New	360.00	360.00
4	TO DRILL HOLE AND RE-INSTALL REAR SENSOR	New	180.00	180.00
5	TO REMOVE ALL NECESSARY DAMAGED PARTS, REPLACE, REPAIR END PANEL, REINFORCEMENT, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR	New	3,600.00	1,440.00
6	TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR	New	3,540.00	1,770.00
Gross Labour Cost (S\$)			7,982.40	4,052.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >