

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005119/KEA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800059655

Claimant
Vehicle No : SMR5354Y **Insured Vehicle No :** GBH371M

Date of Loss: 06/04/2020 Nature of Claim: TP Claim No: 9369468662SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR5354Y	Engine No:	G4FGKU475282
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU010783
Reg. Date:	13/01/2020 (Man. Year: 2019)	Odometer:	14565 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,525.36	7,198.08	5,327.28	42.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	2,350.00	1,020.00	30.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,895.36	9,548.08	6,347.28	39.93
+ GST 7.00/7.00% (\$\$)	1,112.68	668.37	444.31	39.93
Nett Amount (\$\$)	17,008.04	10,216.45	6,791.59	39.93
+ Loss of Use (11.0 x S\$80.00/day) (\$\$)		880.00		
+ Doc/Search Fee (\$\$)		2.00		
+ Other Costs (\$\$)		100.00		
Nett Liability (\$\$)		11,198.45		

INSPECTION

Date of Assignment: 13/04/2020

Date Inspected: 13/04/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	1,467.50 FL	*1,467.50 FL
2	1		*FRONT DOOR OUTER HANDLE RH	Broken	121.60 FL	*121.60 FL
3	1		*FRONT DOOR OUTER HANDLE BASE RH	Missing	105.70 FL	*105.70 FL
4	1		*FRONT DOOR OUTER HANDLE COVER RH	Missing	45.00 FL	*45.00 FL
5	1		*FRONT DOOR CYLINDER KEYLOCK RH	Missing	240.00 FL	*240.00 FL
6	10		*FRONT DOOR INNER TRIM CLIPS RH	Not Necessary	65.00 FL	*- FL
7	1		*FRONT DOOR FRAME PROTECTIVE STICKER RH	Necessary	40.00 FL	*40.00 FL
8	1		*FRONT DOOR POWER WINDOW GEAR ASSY RH	Serviceable	1,150.10 FL	*- FL
9	1		*FRONT DOOR WINDOW GLASS RH	Serviceable	485.50 FL	*- FL
10	1		*FRONT DOOR GLASS OUTER MOULDING RH	Serviceable	79.50 FL	*- FL
11	1		*REAR DOOR RH	Bent	1,476.80 FL	*1,476.80 FL
12	1		*REAR DOOR INNER LOCK RH	Jammed	257.20 FL	*257.20 FL
13	1		*REAR DOOR OUTER HANDLE RH	Mtg Cracked	121.60 FL	*121.60 FL
14	1		*REAR DOOR OUTER HANDLE INNER BASE RH	Serviceable	105.70 FL	*- FL
15	1		*REAR DOOR FRAME PROTECTIVE STICKER RH	Necessary	40.00 FL	*40.00 FL
16	10		*REAR DOOR INNER TRIM CLIP RH	Not Necessary	65.00 FL	*- FL
17	1		*REAR QUARTER PANEL RH	Bent	1,852.50 FL	*1,768.30 FL
18	12		*REAR QUARTER PANEL INNER TRIM COVERING CLIPS	Not Necessary	81.60 FL	*- FL
19	1		*REAR ALLOY RIM RH	Dented	895.20 FL	*895.20 FL
20	1		*REAR AXLE BEAM ASSY	Serviceable	2,025.00 FL	*- FL
21	1		*REAR WHEEL BEARING ASSY RH	Not Necessary	402.70 FL	*- FL
22	1		*REAR TAIL LAMP RH	Broken	482.50 FL	*482.50 FL
23	1		*REAR TAIL LAMP PANEL RH	Repair	338.20 FL	*- FL
24	1		*REAR BUMPER	Mtg Cracked	980.00 FL	*654.30 FL
25	1		*REAR BUMPER SIDE BRACKET RH	Distorted	58.00 FL	*58.00 FL
26	1		*REAR FENDER INNER LINER RH	Repair	328.60 FL	*- FL
27	8		*REAR BUMPER CLIPS	Necessary	46.40 FL	*46.40 FL
28	1		*REAR BUMPER LOWER LAMP RH	Serviceable	476.00 FL	*- FL
29	1		*REAR BUMPER LOWER LAMP GARNISH	Serviceable	596.30 FL	*- FL
30	1		*REAR WINDSCREEN GLASS	Shattered	945.00 FL	*945.00 FL
31	1		*REAR WINDSCREEN RUBBER	Necessary	120.00 FL	*120.00 FL
32	1		*REAR BOOT (NPA)	Repair	0.00 FL	*- FL
33	1		*REAR QUARTER PANEL LOWER SILL MEMBER RH (NPA)	Repair	0.00 FL	*- FL
34	1		*RUNNING BOARD PANEL RH (NPA)	Repair	0.00 FL	*- FL
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	2		*REAR WINDSCREEN STOPPER	Necessary	30.00 FS	*30.00 FS
37	1		*REAR WINDSCREEN DECAL STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,624.20** **8,975.10**
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,098.84 1,777.02
Total Parts (\$\$) **12,525.36** **7,198.08**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	1,000.00	900.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH ,REAR DOOR RH ,REAR QUARTER PANEL RH ,REAR BUMPER ,REAR BOOT LID ,RUNNING BOARD PANEL RH & ETC	New	1,300.00	1,100.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM & ETC ,BACK TO ORIGINAL OPERATIONS	New	240.00	120.00
4	LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC	New	80.00	30.00
5	LABOUR CHARGES TO REMOVE ,REFIX ,REPLACE REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT & ETC	New	120.00	120.00
6	LABOUR CHARGES TO REMOVE ,REPLACE & READJUST REAR ABSORBER ,REAR AXLE BEAM ASSY ,REAR WHEEL BEARING & ETC	New	350.00	0.00
7	LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC	New	80.00	20.00
8	TO WHEEL ALIGNMENT & BALANCING	New	80.00	60.00
9	TO DIAGNOSE FAULTY CODE & RESET MEMORY	New	120.00	0.00
Gross Labour Cost (\$\$)			3,370.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >