



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2003731
INV Date 08/05/2020
Reference CS/AGI20005122/Atf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLN 4721K

Insured Veh. SKJ 8621Y

Claim No. C10005302

Policy No.

Accident Date 18/01/2020

Inspection Date 14/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005122/Atf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 08-05-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 8621Y	Veh. Inspected	SLN 4721K
Policy No.		Coverage (\$)	0.00
Claim No.	C10005302	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	09/04/2020

2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA HB	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LBE6EC4HG017790	Colour	GREEN
Odometer	56265	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	6 mm
L/H Front Tyre	225/45 R17	MICHELIN	6 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/01/2020	Inspection Date	14/04/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4721K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	1,994.00	1,660.00
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$106.00	O/S NECESSARY	212.00	106.00
1	FRONT R/H BUMPER FOG LAMP	CRACKED	434.00	295.00
1	FRONT R/H BUMPER FOG LAMP COVER	CUT	105.00	105.00
1	FRONT R/H BUMPER FOG LAMP LOWER COVER	NOT NECESSARY	69.00	-
1	FRONT R/H HEADLAMP	CUT	1,260.00	1,260.00
1	FRONT R/H HEADLAMP LOWER BRACKET	NOT NECESSARY	79.00	-
1	FRONT R/H FENDER	TO REPAIR SEE LABOUR	682.00	-
1	FRONT R/H FENDER COWLING	NOT NECESSARY	138.00	-
8	FRONT R/H FENDER COWLING CLIP @\$6.50	NOT NECESSARY	52.00	-
1	FRONT R/H TYRE	NOT NECESSARY	380.00	-
	LESS 10% DISCOUNT		-	-345.60
			5,470.00	3,110.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT R/H RIM (SN)	CUT	1,200.00	700.00
			1,200.00	700.00
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT COMPUTER.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT R/H FENDER.		800.00	300.00
	SPRAY PAINTING.		1,000.00	400.00
	-		-	-
	-		-	-
	-		-	-
			2,200.00	810.00
	GRAND TOTAL		8,870.00	4,620.40

Report Ref No. CS/AGI20005122/Atf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	-----------------

Report Ref No. CS/AGI20005122/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4721K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



WOLBE6EC4HG017790



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4721K

RE-INSPECTION

