



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 534D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	480.00	480.00
1	LH REAR BUMPER MOUNTING	SERVICEABLE	28.00	-
1	RH REAR BUMPER MOUNTING	SERVICEABLE	28.00	-
1	REAR LOWER SPOILER	CUT	300.00	300.00
1	RH OUTER TAILLIGHT	NOT NECESSARY	400.00	-
1	RH INNER TAILLIGHT	NOT NECESSARY	400.00	-
	LESS 20% DISCOUNT		-	-156.00
			1,636.00	624.00
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	60.00	20.00
			60.00	20.00
	<u>LABOUR</u>			
	REMOVAL, REFITTING AND TRANSFERRING OF WIRESETS FOR REAR BUMPER COVER AND TAILLAMPS.		400.00	250.00
	SURFACE PREPARATION, SPRAY PAINT AND POLISH OF REAR BUMPER AND BOOTLID.		600.00	250.00
	TO PERFORM PARKING AID TEST, DIAGNOSTICS AND CLEARING OF FAULT CODES AFTER REPAIR.	NOT NECESSARY	120.00	-
			1,120.00	500.00
GRAND TOTAL			2,816.00	1,144.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00
---	--	--	---------------

Report Ref No. CS/UOI20005127/R1yf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.