

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005130/GDS3Q2

Date: 06/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMM1951B	Insured Vehicle No :	SH6494B
Date of Loss: 30/03/2020	Nature of Claim: TP	Claim No: MCT20030486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1951B		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A6000023
Reg. Date:	16/12/2010 (Man. Year: 2010)	Chassis No:	GE63000023
Colour:	White	Odometer:	174048 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,678.00	1,260.32	22,417.68	94.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,380.00	1,560.00	5,820.00	78.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,058.00	2,820.32	28,237.68	90.92
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	31,058.00	2,200.00	28,858.00	92.92
+ GST 7.00/7.00% (S\$)	2,174.06	154.00	2,020.06	92.92
Nett Amount (S\$)	33,232.06	2,354.00	30,878.06	92.92
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		3,254.00		

INSPECTION

Date of Assignment:	09/04/2020	
Date Inspected:	09/04/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1951B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP (RH)	Not Necessary	927.00 F	*- FL
2	1		*TAIL LAMP PANEL (RH)	Not Necessary	492.00 F	*- FL
3	1		*REAR DOOR (RH)	Repair	1,016.00 F	*- FL
4	1		*REAR DOOR HANDLE (RH)	Not Necessary	349.00 F	*- FL
5	1		*REAR DOOR INNER BOARD (RH)	Not Necessary	789.00 F	*- FL
6	1		*REAR DOOR INNER BOARD SWITCH (RH)	Not Necessary	811.00 F	*- FL
7	1		*REAR DOOR LOCK(RH)	Not Necessary	412.00 F	*- FL
8	1		*REAR DOOR LOCK CATCH (RH)	Not Necessary	92.00 F	*- FL
9	2		*REAR DOOR HINGE (UPPER AND LOWER) (RH)	Not Necessary	322.00 F	*- FL
10	1		*REAR DOOR CHECKER (RH)	Not Necessary	181.00 F	*- FL
11	1		*REAR DOOR POWER WINDOW (RH)	Not Necessary	497.00 F	*- FL
12	1		*REAR DOOR WINDOW REGULATOR (RH)	Not Necessary	411.00 F	*- FL
13	1		*REAR DOOR WINDOW MOULDING (RH)	Not Necessary	135.00 F	*- FL
14	1		*REAR DOOR WEATHERSTRIP (RH)	Not Necessary	217.00 F	*- FL
15	1		*REAR DOOR INNER WEATHERSTRIP (RH)	Not Necessary	219.00 F	*- FL
16	1		*ROCKER PANEL (RH)	Not Necessary	1,061.00 F	*- FL
17	1		*ROCKER PANEL GARNISH (RH)	Not Necessary	452.00 F	*- FL
18	1		*REAR FENDER (RH)	Buckled	1,819.00 F	*881.20 FL
19	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	841.00 F	*- FL
20	1		*REAR FENDER COWLING (RH)	Not Necessary	211.00 F	*- FL
21	1		*REAR QUARTER WINDOW REGULATOR (RH)	Necessary	309.00 F	*88.00 FL
22	1		*REAR BUMPER	Cut	1,061.00 F	*468.20 FL
23	1		*REAR BUMPER RETAINER (RH)	Deformed	134.00 F	*25.50 FL
24	1		*REAR BUMPER BRACKET (RH)	Not Necessary	159.00 F	*- FL
25	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Not Necessary	0.00 F	*- FL
26	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 F	*- FL
27	2		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	894.00 F	*- FL
28	1		*REAR ABSORBER (RH)	Not Necessary	461.00 F	*- FL
29	1		*REAR BEARING HUB (RH)	Not Necessary	446.00 F	*- FL
30	1		*REAR AXLE	Not Necessary	2,146.00 F	*- FL
31	2		*SET REAR RIM	Repair	4,372.00 F	*- FL
32	2		*SET REAR TYRE	Not Necessary	1,642.00 F	*- FL
33	2		*TAIL LAMP CLIPS	Not Necessary	40.00 FS	*- FS
34	10		*REAR DOOR INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
36	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
37	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
38	10		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
39	1		*REAR FENDER QUARTER WINDOW SEALANT	Necessary	120.00 FS	*40.00 FS
40	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 23,678.00 1,552.90
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 292.58

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					23,678.00	1,260.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN	New	2,400.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,400.00	680.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	60.00
4	TO RNR UPHOLSTERY GARNISH AND ATTACHMENT PARTS	New	400.00	60.00
5	TO RNR DOOR MECHANISM	New	400.00	0.00
6	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	40.00
7	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
8	TO CHECK WHEEL ALIGNMENT	New	250.00	60.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	30.00
10	TO RNR TYRE AND WHEEL BALANCING	New	250.00	30.00
11	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	400.00	0.00
12	TO DO WATER LEAK TEST	New	80.00	0.00
Gross Labour Cost (\$)			7,380.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >