

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005134/AGA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMF9776A **Insured Vehicle No :** SJG9601B

Date of Loss: 02/04/2020 **Nature of Claim:** TP **Claim No:** 0590418824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9776A		
Make & Model:	TOYOTA PRIUS ALPHA, 1.8 (A)	Engine No:	2ZR0B45565
Reg. Date:	30/11/2018 (Man. Year: 2018)	Chassis No:	ZVW400029136
Colour:	Brown	Odometer:	140258 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,676.88	1,026.75	4,650.13	81.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	630.00	3,350.00	84.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,656.88	1,656.75	8,000.13	82.84
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	9,656.88	1,300.00	8,356.88	86.54
+ GST 7.00/7.00% (S\$)	675.98	91.00	584.98	86.54
Nett Amount (S\$)	10,332.86	1,391.00	8,941.86	86.54
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,667.45		

INSPECTION

Date of Assignment: 09/04/2020

Date Inspected: 13/04/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER GLASS RH	Not Necessary	546.40 FL	*- FL
2	1		*REAR FENDER COWLING RH	Not Necessary	135.80 FL	*- FL
3	1		*REAR WHEEL SPORT RIM RH	Cut	840.45 FS	*500.00 FS
4	1		*REAR WHEEL HUP CAP RH	Cut	147.53 FS	*100.00 FS
5	1		*REAR WHEEL HUP RH	Not Necessary	453.20 FL	*- FL
6	1		*REAR WHEEL HUP BEARING RH	Not Necessary	156.10 FL	*- FL
7	1		*REAR SHOCK ABSORBER RH	Not Necessary	362.90 FL	*- FL
8	1		*TAILLAMP LOWER BRACKET RH	Not Necessary	69.30 FL	*- FL
9	1		*REAR BUMPER	Deformed	968.70 FL	*459.20 FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	84.20 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	139.60 FL	*69.80 FL
12	1		*REAR FENDER RH	Not Necessary	1,390.60 FL	*- FL
13	1		*REAR FENDER AIR VENT RH	Not Necessary	78.40 FL	*- FL
14	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
15	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
16	1		*REAR FENDER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
17	1		*REAR FENDER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS
18	1		*REAR FENDER GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
19	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
20	1		*SET TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
21	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
22	1		*REAR WHEEL TYRE RH	Not Necessary	680.00 FS	*- FS
23	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,773.18	1,159.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,096.30	132.25
Total Parts (\$)	5,676.88	1,026.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,000.00	250.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	250.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	180.00	0.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	350.00	0.00
9	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	REMOVE AND REFIX REAR FENDER GLASS RH	New	100.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			3,980.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >