

WG APPRAISAL SERVICES

Bik 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : GAN EE ZHONG JEREMY
C/O MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Date : 15 October 2019
Our Ref : WG/TP/2019-404

REFERENCE PARTICULARS

Date of Accident : 07 September 2019
Date of Inspection : 10 September 2019

Type of Inspection : Third Party Claim
Date of Re-Inspn : 18 September 2019

VEHICLE PARTICULARS

Registration No : FW4593L
Make : HONDA
Model : VFR800A2
Year : 2002

Engine No : RC46E2418176
Chassis No : JH2RC46C62M404611
Odometer : 1096km
Colour : Silver

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front side	: Pirelli	120/70ZR17
Rear Side	: Pirelli	180/55ZR17

Thread Balance
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$8,050.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Sixty-six (66) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

In accordance to your instruction, we have **not** authorise repairs and inspection
was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : FW4593L
MODEL : VFR800A2

Our Ref : WG/TP/2019-403

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 FRONT HEADLAMP <i>xnn</i>	1	NOT NECESSARY	\$ 800.00	\$ -
2 HEADLAMP FAIRING <i>scr</i>	1	GRAZED	\$ 1,100.00	\$ 1,100.00 <i>\$800</i>
3 FRONT SIGNAL LAMP RH <i>ora</i>	1	CRACKED	\$ 150.00	\$ 150.00 <i>\$80</i>
4 FRONT FEDNER <i>ora</i>	1	CRACKED	\$ 350.00	\$ 350.00 <i>\$250</i>
5 BRAKE LEVER <i>ora</i>	1	GRAZED	\$ 250.00	\$ 250.00 <i>\$80</i>
6 BALANCER <i>scr</i>	1	GRAZED	\$ 210.00	\$ 210.00 <i>\$150</i>
7 RH FOOTREST <i>ora</i>	1	BENT	\$ 220.00	\$ 220.00 <i>\$170</i>
8 RH FOOTREST BRACKET <i>ora</i>	1	BENT	\$ 310.00	\$ 310.00
9 RH PILLION FOOTREST BRACKET <i>xnn</i>	1	NOT NECESSARY	\$ 220.00	\$ -
10 WING MIRROR <i>cut</i>	1	GRAZED	\$ 230.00	\$ 230.00 <i>\$120</i>
11 RH SIDE FARING <i>scr</i>	1	GRAZED	\$ 950.00	\$ 950.00 <i>\$650</i>
12 REAR RH FAIRING <i>scr</i>	1	GRAZED	\$ 630.00	\$ 630.00 <i>\$450</i>
13 FUEL TANK <i>xnn</i>	1	DENTED	\$ 1,120.00	\$ 1,120.00
14 HANDLE BAR <i>xnn</i>	1	NOT NECESSARY	\$ 550.00	\$ -
15 HANDLE BAR GRIP <i>xnn</i>	1	NOT NECESSARY	\$ 210.00	\$ -
16 FRONT LH FORK ASSY <i>xnn</i>	1	BENT	\$ 550.00	\$ 550.00
17 FRONT RH FORK ASSY <i>xnn</i>	1	BENT	\$ 750.00	\$ 750.00
18 STEERING HEADCROWM <i>xnn</i>	1	NECESSARY	\$ 750.00	\$ 750.00
19 STEERING STEM UNDERBRACKET <i>xnn</i>	1	NECESSARY	\$ 195.00	\$ 195.00
20 STEERING STEM BEARING <i>xnn</i>	1	NECESSARY	\$ 240.00	\$ 250.00
21 REAR EXHAUST <i>x(R)</i>	1	GRAZED	\$ 1,690.00	\$ 1,690.00
			\$ 11,475.00	\$ 9,705.00
		Less 10%	\$ 1,147.50	\$ 970.50
			\$ 10,327.50	\$ 8,734.50

B) S/NETT ITEM

22 GEAR SHIT SHAFT OIL SEAL <i>xnn</i>	1 SET	NECESSARY	\$ 24.00	\$ 24.00
23 FORK OIL SEAL <i>xnn</i>	2	NECESSARY	\$ 120.00	\$ 129.00
24 FORK OIL <i>xnn</i>	1 BOT	NECESSARY	\$ 60.00	\$ 60.00
			\$ 204.00	\$ 213.00

Parts Total :

\$ 10,531.50	\$ 8,947.50
--------------	-------------

C) LABOUR CHARGES & MISC

25 REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM			\$ 600.00	\$ 400.00 <i>\$320</i>
26 TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING			\$ 380.00	\$ 250.00
27 TO REMOVE/REFIT, REPLACE FRONT FORK TUDES			\$ 180.00	\$ 150.00
28 SPRAY PAINTING			\$ 380.00	\$ 300.00 <i>\$1020</i>
		Labour Total :	\$ 1,540.00	\$ 1,100.00

Total Parts and Laboure :

\$ 12,071.50	\$ 10,047.50
--------------	--------------

FINAL LUMP SUM ADJUSTMENT

Lst item : \$ 2805
 Net item : 0
 Labour : \$1020
 Total : \$3828
 L/S : \$3050 / =

\$ 8,050.00

POINT OF IMPACT

The impact was confined to the front left portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$8,050.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES

Winson
Automotive

