



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 4593L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP	SERVICEABLE	800.00	-
1	HEADLAMP FAIRING	SCRATCHED	1,100.00	800.00
1	FRONT SIGNAL LAMP RH	CRACKED	150.00	80.00
1	FRONT FENDER	CRACKED	350.00	250.00
1	BRAKE LEVER	CUT	250.00	80.00
1	BALANCER	SCRATCHED	210.00	150.00
1	RH FOOTREST	BENT	220.00	170.00
1	RH FOOTREST BRACKET	BENT	310.00	310.00
1	RH PILLION FOOTREST BRACKET	SERVICEABLE	220.00	-
1	WING MIRROR	CUT	230.00	120.00
1	RH SIDE FAIRING	SCRATCHED	950.00	680.00
1	REAR RH FAIRING	SCRATCHED	630.00	480.00
1	FUEL TANK	SERVICEABLE	1,120.00	-
1	HANDLE BAR	SERVICEABLE	550.00	-
1	HANDLE BAR GRIP	SERVICEABLE	210.00	-
1	FRONT LH FORK ASSY	SERVICEABLE	550.00	-
1	FRONT RH FORK ASSY	SERVICEABLE	750.00	-
1	STEERING HEADCROWM	SERVICEABLE	750.00	-
1	STEERING STEM UNDERBRACKET	SERVICEABLE	195.00	-
1	STEERING STEM BEARING	SERVICEABLE	240.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,690.00	-
	LESS 10% DISCOUNT		-1,147.50	-312.00
			10,327.50	2,808.00
<u>SPECIAL NETT ITEMS</u>				
1	SET GEAR SHIT SHAFT OIL SEAL (SN)	NOT NECESSARY	24.00	-
2	FORK OIL SEAL (SN)	NOT NECESSARY	120.00	-
1	BOT FORK OIL (SN)	NOT NECESSARY	60.00	-
			204.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM. INCLUSIVE OF THE REPAIR OF REAR EXHAUST.		600.00	320.00
	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING.		380.00	250.00
	TO REMOVE/REFIT, REPLACE FRONT FORK TUBES.		180.00	150.00
	SPRAY PAINTING.		380.00	300.00
			1,540.00	1,020.00
	GRAND TOTAL		12,071.50	3,828.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00

Report Ref No. CS/III19016022/Fsf3e2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.