



INVOICE

TO : KOH HWA CHANG
C/O: EURO ASIA MOTORSPORT PTE LTD
56 LOYANG WAY, LOYANG
ENTERPRISE BUILDING #01-02
SINGAPORE 508775

Invoice No.: 1119/EA371
Date: 20-Dec-2019

PARTICULARS

Vehicle Registration No.: SLP 1638 C
Date of Loss: 15-Nov-2019
Date of Assessment: 18-Nov-2019

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$450.00

TOTAL \$450.00

SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: KOH HWA CHANG
C/O: EURO ASIA MOTORSPORT PTE LTD
56 LOYANG WAY, LOYANG
ENTERPRISE BUILDING #01-02
SINGAPORE 508775

Our Reference: 1119/EA371
Date: 20-Dec-2019

ASSESSMENT OF VEHICLE NO. SLP 1638 C
DATE OF LOSS: 15-Nov-2019

We have carried out a physical assessment at **EURO ASIA MOTORSPORT PTE LTD**,
56 Loyang Way, Loyang Enterprise Building #01-02, Singapore 508775, according to your instruction
on **18-Nov-2019** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SLP 1638 C
Make & Model: TOYOTA COROLLA ALTIS 1.6 AUTO
Year of Registration: 2010
Engine Capacity: 1598
Chassis No.: MR053ZEE106174530
Engine No.: 3ZZ4996308
Colour: WHITE
Mileage (km): 286055

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: CONTINENTAL 195/65 R15 – 70%
LH Make/Size/Thread: CONTINENTAL 195/65 R15 – 70%


Rear
RH Make/Size/Thread: CONTINENTAL 195/65 R15 – 70%
LH Make/Size/Thread: CONTINENTAL 195/65 R15 – 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$7,499.01
Adjusted Amount:	\$5,366.91
Lump Sum:	\$4,200.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a “**Without Prejudice**” basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SLP 1638 C

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Repair	631.70	-
1	REAR RH TAILLAMP	Cracked	361.70	361.70
1	REAR RH TAILLAMP CLIPS	Necessary	6.50	6.50
1	REAR RH TAILLAMP BACK RUBBER GASKET	Necessary	43.55	43.55
1	REAR RH TAILLAMP LOWER BRACKET	Bent	135.55	135.55
1	REAR RH TAILLAMP INNER PANEL	Bent	181.90	181.90
1	REAR RH FENDER	Bent	806.10	806.10
1	REAR RH FENDER INNER PANEL	Bent	236.00	236.00
1	REAR RH FENDER INNER UPHOLSTERY TRIM	Cut	327.00	327.00
1	REAR RH FENDER INNER AIR VENT	Cracked	100.45	100.45
1	REAR BUMPER	Cracked	561.70	561.70
2	REAR BUMPER CORNER RETAINER L/R	Bent	78.80	78.80
2	REAR BUMPER IMPACT BRACKET L/R	Bent	96.60	96.60
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	Necessary	39.00	39.00
2	REAR BUMPER INNER SIDE SHIELD L/R	Cracked	262.70	262.70
1	REAR BUMPER INNER SPONGE	Cracked	121.40	121.40
2	REAR BUMPER REFLECTOR L/R	Necessary	138.80	138.80
2	REAR BUMPER SIDE RETAINER L/R	Bent	98.80	98.80
1	REAR END PANEL INNER TOP GANRISH	Repair	101.70	-
4	REAR END PANEL INNER TOP GANRISH CLIPS	Necessary	26.00	26.00
1	REAR END PANEL	Repair	667.70	-
1	REAR EXHAUST SILENCER BOX	Repair	801.70	-
			<u>5,825.35</u>	<u>3,622.55</u>
Less 25% discount			<u>1,456.34</u>	<u>905.64</u>
Parts Total:			<u>4,369.01</u>	<u>2,716.91</u>

ASSESSMENT REPORT FOR VEHICLE NO. SLP 1638 C

SPECIAL NETT ITEMS

1	REAR BUMPER CLIPS - SET	Necessary	30.00	30.00
1	REAR BUMPER REVERSE SENSOR - SET	Faulty	350.00	350.00
1	REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET	Necessary	30.00	30.00
Special Nett Total :			410.00	410.00

LABOUR


S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	100.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00	80.00
3	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00	80.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	800.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,300.00	1,100.00
6	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00
Labour Total :		2,720.00	2,240.00
TOTAL (PARTS & LABOUR) \$		7,499.01	5,366.91

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$4,200.00

(SINGAPORE DOLLARS FOUR THOUSAND TWO HUNDRED ONLY)



Amas Ong
Automobile Assessor

EURO ASIA MOTORSPORT PTE LTD

**56 LOYANG WAY, LOYANG
ENTERPRISE BUILDING #01-02
SINGAPORE 508775
TEL : 6509 0337 FAX:6509 0367
EMAIL: enquiries@eamotorwerkz.com.sg**

TO : IKOH HWA CHANG
AS PER REPORT
SINGAPORE

Our Reference:	ALTIS/SLP1638C
Date:	20-Dec-2019
Vehicle Num:	SLP 1638 C
Make/Model:	TOYOTA COROLLA ALTIS 1.6 AUTO
Chassis No.:	MR053ZEE106174530
Engine No.:	3ZZ4996308
Accident Date:	15-Nov-2019

[illegible]