

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19020488/FVF3E2-1
Date: 17/04/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000955317
Claimant Vehicle No :	SLP1638C	Insured Vehicle No :	SLX6540A
Date of Loss:	15/11/2019	Nature of Claim:	TP
		Claim No:	233514

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1638C	Engine No:	3ZZ4996308
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106174530
Reg. Date:	07/06/2010 (Man. Year: 2010)	Odometer:	286055 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,779.01	2,105.95	2,673.06	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,360.00	1,360.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,499.01	3,465.95	4,033.06	53.78
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	7,499.01	2,750.00	4,749.01	63.33

INSPECTION

Date of Assignment:	27/11/2019	
Date Inspected:	19/11/2019 Inspected At:	56 LOYANG WAY#04-04 Repairer : Euro Asia Motorsport Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: PARASURAM SHANMUGAM**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP1638C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	631.70 FL	*- FL
2	1		*REAR RH TAILLAMP	Cracked	361.70 FL	*361.70 FL
3	1		*REAR RH TAILLAMP CLIPS	Necessary	6.50 FL	*6.50 FL
4	1		*REAR RH TAILLAMP BACK RUBBER GASKET	Serviceable	43.55 FL	*- FL
5	1		*REAR RH TAILLAMP LOWER BRACKET	Serviceable	135.55 FL	*- FL
6	1		*REAR RH TAILLAMP INNER PANEL	Buckled	181.90 FL	*181.90 FL
7	1		*REAR RH FENDER	Buckled	806.10 FL	*708.00 FL
8	1		*REAR RH FENDER INNER PANEL	Repair	236.00 FL	*- FL
9	1		*REAR RH FENDER INNER UPHOLSTERY TRIM	Serviceable	327.00 FL	*- FL
10	1		*REAR RH FENDER INNER AIR VENT	Serviceable	100.45 FL	*- FL
11	1		*REAR BUMPER	Cracked	561.70 FL	*561.70 FL
12	1		*REAR BUMPER CORNER RETAINER L/R	O/S Necessary	78.80 FL	*39.40 FL
13	1		*REAR BUMPER IMPACT BRACKET L/R	O/S Broken	96.60 FL	*48.30 FL
14	6		*REAR BUMPER INNER SIDE SHIELD CLIPS L/R	Necessary	39.00 FL	*39.00 FL
15	2		*REAR BUMPER INNER SIDE SHIELD L/R	Cracked	262.70 FL	*262.70 FL
16	1		*REAR BUMPER INNER SPONGE	Cracked	121.40 FL	*121.40 FL
17	2		*REAR BUMPER REFLECTOR L/R	Serviceable	138.80 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINER L/R	Bent	98.80 FL	*78.00 FL
19	1		*REAR END PANEL INNER TOP GARNISH	Serviceable	101.70 FL	*- FL
20	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00 FL	*26.00 FL
21	1		*REAR END PANEL	Repair	667.70 FL	*- FL
22	1		*REAR EXHAUST SILENCER BOX	Repair	801.70 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	350.00 FS	*220.00 FS
25	1		*SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,235.35	2,714.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,456.34	608.65

Total Parts (\$\$)	4,779.01	2,105.95
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	80.00
2	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	100.00	50.00
3	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	50.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	550.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,300.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
Gross Labour Cost (S\$)			2,720.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >