

ASSESSMENT REPORT FOR VEHICLE NO. SLP 1638 C

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID <i>x(R)</i>	Repair	631.70	-
1	REAR RH TAILLAMP <i>cra</i>	Cracked	361.70	361.70 ✓
1	REAR RH TAILLAMP CLIPS <i>nec</i>	Necessary	6.50	6.50 ✓
1	REAR RH TAILLAMP BACK RUBBER GASKET <i>nec</i>	Necessary	43.55	<i>\$23</i> 43.55 ✓
1	REAR RH TAILLAMP LOWER BRACKET <i>xnn</i>	Bent	135.55	135.55 ✓
1	REAR RH TAILLAMP INNER PANEL <i>Buc</i>	Bent	181.90	181.90 ✓
1	REAR RH FENDER <i>Buc</i>	Bent	806.10	<i>\$708</i> 806.10 ✓
1	REAR RH FENDER INNER PANEL <i>x(R)</i>	Bent	236.00	236.00 ✓
1	REAR RH FENDER INNER UPHOLSTERY TRIM <i>xnn</i>	Cut	327.00	327.00 ✓
1	REAR RH FENDER INNER AIR VENT <i>x(R)</i>	Cracked	100.45	100.45 ✓
1	REAR BUMPER <i>cra</i>	Cracked	561.70	561.70 ✓
2	REAR BUMPER CORNER RETAINER L/R <i>nec (R only)</i>	Bent	78.80	78.80 ✓
2	REAR BUMPER IMPACT BRACKET L/R <i>Br (R only)</i>	Bent	96.60	96.60 ✓
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R <i>nec</i>	Necessary	39.00	39.00 ✓
2	REAR BUMPER INNER SIDE SHIELD L/R <i>cra</i>	Cracked	262.70	262.70 ✓
1	REAR BUMPER INNER SPONGE <i>cra</i>	Cracked	121.40	121.40 ✓
2	REAR BUMPER REFLECTOR L/R <i>xnn</i>	Necessary	138.80	138.80 ✓
2	REAR BUMPER SIDE RETAINER L/R <i>Bt</i>	Bent	98.80	<i>\$78</i> 98.80 ✓
1	REAR END PANEL INNER TOP GANRISH <i>xnn(R)</i>	Repair	101.70	-
4	REAR END PANEL INNER TOP GANRISH CLIPS <i>nec</i>	Necessary	26.00	26.00 ✓
1	REAR END PANEL <i>x(R)</i>	Repair	667.70	-
1	REAR EXHAUST SILENCER BOX <i>x(R)</i>	Repair	801.70	-
			5,825.35	3,622.55
Less 25% discount			1,456.34	905.64
Parts Total:			4,369.01	2,716.91

\$2545.30
aft 25% = \$1908.97

ASSESSMENT REPORT FOR VEHICLE NO. SLP 1638 C

SPECIAL NETT ITEMS

1	REAR BUMPER CLIPS - SET <i>nec</i>	Necessary	30.00	30.00
1	REAR BUMPER REVERSE SENSOR - SET <i>ec</i>	Faulty	350.00 <i>\$220</i>	350.00
1	REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>nec</i>	Necessary	30.00	30.00
Special Nett Total :			410.00	410.00

LABOUR


S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	<i>\$80</i> 100.00 120.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00	<i>\$50</i> 80.00
3	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00	<i>\$50</i> 80.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	<i>\$550</i> 800.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,300.00	<i>\$600</i> 1,100.00
6	To apply anti-rust chemical on repaired and replaced panel.	100.00	<i>\$30</i> 80.00
Labour Total :		2,720.00	2,240.00
TOTAL (PARTS & LABOUR) \$		7,499.01	5,366.91

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$4,200.00

(SINGAPORE DOLLARS FOUR THOUSAND TWO HUNDRED ONLY)



Amas Ong
Automobile Assessor

LIST ITEM : \$ 1908.97

NETT ITEM : \$280

LABOUR : \$1360

Total : \$3548.97

L/S : \$2800 / =

Repair days :