

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20005141/UKA3Q2

**Date:** 17/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994005

**Claimant**  
**Vehicle No :** SJT2606R **Insured Vehicle No :** YN3397R

Date of Loss: 08/04/2020 Nature of Claim: TP Claim No: 4507559899SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT2606R**  
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H287154  
 Reg. Date: 30/09/2009 (Man. Year: 2009) Chassis No: KNAFW411MA5118635  
 Colour: Grey Odometer: 182841 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,372.40	1,715.40	657.00	27.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,550.00	620.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,542.40</b>	<b>3,265.40</b>	<b>1,277.00</b>	<b>28.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	4,542.40	2,600.00	1,942.40	42.76
<b>+ GST 7.00/7.00% (S\$)</b>	317.97	182.00	135.97	42.76
<b>Nett Amount (S\$)</b>	<b>4,860.37</b>	<b>2,782.00</b>	<b>2,078.37</b>	<b>42.76</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>Nett Liability (S\$)</b>		<b>3,022.00</b>		

### INSPECTION

Date of Assignment: 13/04/2020

Date Inspected: 20/04/2020 Inspected At:

Jin Auto Services Pte Ltd (Defu)  
 Blk 14 Defu Lane 10, #01-410/412  
 Singapore 539195

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed/Torn	601.00 FL	*601.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER LOWER BLACK GARNISH	Torn	122.00 FL	*122.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	304.00 FL	*304.00 FL
5	1		*END PANEL	Dented	282.00 FL	*282.00 FL
6	1		*END PANEL GARNISH	Not Necessary	69.00 FL	*- FL
7	1		*BOOTLID RUBBER	Not Necessary	149.00 FL	*- FL
8	1		*BOOTLID RUBBER BADGE	Necessary	34.00 FL	*34.00 FL
9	1		*BOOTLID CERATO EMBLEM	Necessary	39.00 FL	*39.00 FL
10	2		*PARKING SENSOR	Shorted	428.00 FL	*428.00 FL
11	1		*BOOTLID FORTE EMBLEM	Necessary	36.00 FL	*36.00 FL
12	10		*BOOTLID UPPER LOCK	Serviceable	100.00 FL	*- FL
13	1		*BOOTLID LOWER CATCH	Not Necessary	24.00 FL	*- FL
14	2		*TAILLAMP	Serviceable	388.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,636.00</b>	<b>1,906.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	263.60	190.60
<b>Total Parts (\$\$)</b>	<b>2,372.40</b>	<b>1,715.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	SPRAY PAINT	New	980.00	850.00
2	LABOUR CHARGE TO RENEW AND REFIX PARTS	New	980.00	600.00
3	WIRING	New	30.00	20.00
4	TUFF KOTE	New	120.00	30.00
5	TO REMOVE AND RENEW SENSOR	New	60.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,170.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >