

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005145/KYF3E2

Date: 30/06/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30590919000
Claimant Vehicle No :	SLF6614R	Insured Vehicle No :	GW2233C
Date of Loss:	04/04/2020	Nature of Claim:	TP
		Claim No:	SNM20D201726/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6614R	Engine No:	3A92UDK0669
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH002544
Reg. Date:	05/09/2016 (Man. Year: 2016)	Odometer:	80587 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,417.00	1,143.90	1,273.10	52.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	435.00	1,065.00	71.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,917.00	1,578.90	2,338.10	59.69
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	3,917.00	1,250.00	2,667.00	68.09
+ GST 7.00/7.00% (S\$)	274.19	87.50	186.69	68.09
Nett Amount (S\$)	4,191.19	1,337.50	2,853.69	68.09

INSPECTION

Date of Assignment: 11/06/2020
 Date Inspected: 13/04/2020 Inspected At:

Esteem Performance Pte Ltd - Sin Ming (HQ)
 BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259
SINGAPORE 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jun 2020)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF6614R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS
2	1		*HEADLAMP LH	Serviceable	544.00 F	*- FL
3	1		*FRONT BUMPER	Buckled	666.00 F	*666.00 FL
4	10		*FRONT BUMPER CLIP	Necessary	30.00 F	*30.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	130.00 F	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	19.00 F	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	19.00 F	*- FL
8	1		*FRONT BUMPER BRACKET LH (NPA)	Not Advise	0.00 F	*- FL
9	1		*FRONT BUMPER BRACKET RH (NPA)	Repair	0.00 F	*- FL
10	1		*FRONT BUMPER SPONGE (NPA)	Not Advise	0.00 F	*- FL
11	1		*FRONT GRILLE }	Cracked	525.00 F	*525.00 FL
12	1		*FRONT GRILLE CHROME }		0.00 F	*- FL
13	1		*FRONT EMBLEM	Serviceable	45.00 F	*- FL
14	1		*FOG LAMP LH	Serviceable	274.00 F	*- FL
15	1		*FOG LAMP GARNISH LH	Serviceable	120.00 F	*- FL
16	1		*FOG LAMP CHROME LH (NPA)	Serviceable	0.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,417.00	1,266.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	122.10
Total Parts (\$\$)	2,417.00	1,143.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL)	New	600.00	200.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL)	New	600.00	220.00
3	TO CHECK WIRING, FOCUS HEADLAMP	New	50.00	15.00
4	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS	New	150.00	0.00
5	TO TUFF COAT	New	100.00	0.00
Gross Labour Cost (\$\$)			1,500.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >