

ASS. REC. BY:

REF:

A/G /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04 days

Res.: Yes or No

Lump Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SKG 40863 Yr Regn: 08, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Volkswagen Passat cc 1390

Colour _____

m. Black

AC: Insured / Std / NI / NA

Sp. Reading _____

127035

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WVW ZZZ 3C ZDP 003366

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rlm / STD A/Rlm or _____

Tyre Size: _____

F: _____

215/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

R/Bal. _____

8

mm

Rear

R/Bal. _____

8

mm

L/Bal. _____

8

mm

L/Bal. _____

8

mm

D.O.A. _____

10/4/20

D.O.I. _____

13/4/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / EST NOT ready

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2090359/AMK
Date: 13 Apr 2020
Policy No: 511119231 PREMIUM
Veh Reg No: SKG4086J
Make/Model: VOLKSWAGEN PASSAT 1.4 TSI

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 10/04/2020
TP Veh Reg No: SDU444U

Chassis No: WVWZZZ3CZDP003366
Engine No: CAXB45147
Reg. Date: 30/08/2012

Estimate Repair Cost to Vehicle No :SKG4086J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	1,298.88	1 PC	1,298.88	—
2 FRONT BUMPER REINFORCEMENT	649.44	1 PC	649.44	✓
3 FRONT BUMPER LH SPONGE	142.56	1 PC	142.56	✓
4 FRONT BUMPER LH OUTER PDC SENSOR	186.12	1 PC	186.12	✓
5 FRONT BUMPER LH PARKING SENSOR	186.12	1 PC	186.12	?
6 FRONT BUMPER LH SIDE RETAINER	29.70	1 PC	29.70	✓
7 FRONT BUMPER LH RUNNING LIGHT	257.40	1 PC	257.40	?
8 FRONT BUMPER LH RUNNING LIGHT GARNISH	174.24	1 PC	174.24	✓
9 FRONT BUMPER LH INNER GUIDE	23.76	1 PC	23.76	✓
10 FRONT LH FENDER	643.50	1 PC	643.50	✓
11 FRONT LH FENDER INNER SHIELD	304.92	1 PC	304.92	✓
12 FRONT LH FENDER BRACKET	69.30	1 PC	69.30	?
13 HEADLAMP LH	867.24	1 PC	867.24	✓
			4,833.18	
	Less 10%		483.32	4,349.86
Labour				
14 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,LH HEADLAMP,FRT LH FENDER & REALIGN BONNET THE SAME	450	1 LA	450.00	400
15 PUTTY & RESPRAY FRT BUMPER & LOWER SPOILER,FRT LH FENDER,BONNET,FRT LH DOOR & ALL AFFECTED AREAS	750	1 LA	750.00	600
16 RUSTPROOFING	30	1 LA	30.00	✓
			1,230.00	1,230.00
			Total	SS 5,579.86
			Add GST @ 7%	390.59
			Total Amount Payable	SS 5,970.45

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE