

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 893D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
1	REAR BUMPER REINFORCEMENT	BUCKLED	318.80	318.80
1	REAR BUMPER UNDER SIDE COVER RH	NOT NECESSARY	232.00	-
1	REAR BUMPER LOWER COVER	SCRATCHED	552.60	552.60
1	REAR BUMPER REFLECTOR	NOT NECESSARY	142.00	-
10	REAR BUMPER CLIPS	NOT NECESSARY	25.00	-
	LESS 25% DISCOUNT		-460.43	-332.50
			1,381.27	997.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE / WHOLDER (SN)	DAMAGED	50.00	50.00
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			235.70	50.00
<u>LABOUR</u>				
	PANEL BEATING.		620.00	320.00
	SPRAY PAINTING CHARGE.		400.00	200.00
	TUFF KOTE.		60.00	30.00
	CHECK LIGHTING.		60.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	60.00
			1,200.00	640.00
GRAND TOTAL			2,816.97	1,687.50
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,687.50

Report Ref No. NS/INC20005149/Fsf3e2



PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.