

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

idac

Page No.:1 of 2

Reg. No: 52983356E GST Reg. No. 20-0405911-H

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2546T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR VIEW MIRROR ASSY LH	MISSING	1,390.00	1,390.00
1	OUTER MIRROR COVER LH	MISSING	141.90	141.90
1	FRT DOOR LH	BUCKLED	1,264.00	1,264.00
1	FRT DOOR OUTER HANDLE LH	CUT / BROKEN	378.90	378.90
1	FRT DOOR INNER LOCK LH	NOT NECESSARY	688.80	-
1	FRT DOOR GLASS LH	SCRATCHED	313.60	313.60
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,258.30	-
1	REAR DOOR WEATHERSTRIPE LH	СИТ	176.60	176.60
	LESS 25% DISCOUNT		-1,403.03	-916.25
			4,209.07	2,748.75
	NETT ITEMS			
1	FRT DOOR COMFORT LOGO RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS. STICKER RH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR LH.		700.00	640.00
	SPRAY PAINTING CHARGE.		450.00	400.00
	WIRING CHARGE.		50.00	50.00
	TRANSFER OF DOOR (FRT & REAR).		240.00	100.00
	TUFF KOTE.		50.00	50.00
			-	-
			-	-
			1,490.00	1,240.00
	GRAND TOTAL		5,854.07	4,128.25

RECOMMENDED COST OF LUMP SUM REPAIRS	3,300.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	·

Report Ref No. NS/INC20005151/Fqf3e2





Report Ref No. NS/INC20005151/Fqf3e2

PARASURAM S/O SHANMUGAM

**Asst. Automotive Assessor** 

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser