

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005158/AGA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993936

Claimant
Vehicle No : SJZ8518R **Insured Vehicle No :** GBF9676K

Date of Loss: 09/04/2020 Nature of Claim: TP Claim No: 3680132654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ8518R		
Make & Model:	SUZUKI SX4, 1.6 (A)	Engine No:	M16A1524092
Reg. Date:	30/12/2010 (Man. Year: 2010)	Chassis No:	JSAGYC21S00340039
Colour:	Red	Odometer:	138962 km
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,792.60	2,202.25	5,590.35	71.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,640.00	680.00	29.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,112.60	3,842.25	6,270.35	62.01
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	10,112.60	3,000.00	7,112.60	70.33
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		120.00		
Nett Liability (\$\$)		3,367.45		
Global Sum Settlement (\$\$)		3,350.00		

INSPECTION

Date of Assignment: 11/04/2020

Date Inspected: 11/04/2020 Inspected At:

PERFECT WERKZ
25 KAKI BUKIT ROAD 4 #06-51
SYNERGY @ KB SINGAPORE
417800

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	950.00 F	*- FL
2	1		*FRONT HEAD LAMP -LH	Cracked	1,120.00 F	*438.00 FL
3	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	156.40 F	*- FL
4	1		*FRONT BUMPER	Distorted	950.00 F	*652.00 FL
5	1		*FRONT BUMPER SIDE BRACKET	N/S Damaged	224.00 F	*39.00 FL
6	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
7	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	484.00 F	*- FL
9	1		*FRONT BUMPER LOWER SPOILER	Cracked	800.00 FS	*600.00 FS
10	1		*FRONT BUMPER FOG LAMP -LH	Not Necessary	221.00 F	*- FL
11	1		*FRONT BUMPER FOG LAMP COVER -LH	Cut	88.00 F	*65.00 FL
12	1		*FRONT GRILLE	Not Necessary	215.00 F	*- FL
13	1		*FRONT GRILLE EMBLE LOGO	Not Necessary	56.00 F	*- FL
14	10		*FRONT GRILLE CLIPS	Not Necessary	50.00 F	*- FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	952.00 F	*- FL
16	1		*FRONT SUPPORT PANEL SIDE BRACKET	Not Necessary	65.20 F	*- FL
17	1		*FRONT FENDER -LH	Distorted	524.00 F	*524.00 FL
18	1		*FRONT FENDER COWLING -LH	Torn	112.00 F	*112.00 FL
19	5		*FRONT R/H FENDER COWLING CLIPS	Necessary	25.00 F	*25.00 FL
20	1		*FRONT TYRE -LH	Not Necessary	300.00 F	*- FL
21	2		*FRONT RIM -LH	Not Necessary	400.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,792.60	2,485.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	282.75
Total Parts (\$\$)	7,792.60	2,202.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	0.00
2	WHEEL ALIGNMENT (COMPUTER)	New	120.00	0.00
3	TO CHECK WIRING SYSTEM	New	60.00	30.00
4	TUFF KOTE	New	120.00	50.00
5	TOWING CHARGES	New	200.00	60.00
6	PANEL BEATING	New	900.00	700.00
7	SPRAY PAINTING	New	800.00	800.00
Gross Labour Cost (\$\$)			2,320.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >