

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005168/EYF3E2
Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900120442
Claimant Vehicle No : FBM6014D	Insured Vehicle No :	SBB110G
Date of Loss: 28/03/2020	Nature of Claim:	TP Claim No: 3609838784SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM6014D	Engine No:	HIDDEN
Make & Model:	YAMAHA FZ150I, 150cc	Chassis No:	PMYKG025090005343
Reg. Date:	(Man. Year:)	Odometer:	10667 km
Colour:	Red	Engine Capacity:	150 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-17	Rear Tyre Size:	90/80-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/04/2020	Inspected At:	Moto 51 Pte Ltd (Macpherson)
Date Inspected:	13/04/2020		464 Macpherson Road
			Singapore 368182
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
2	2		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
4	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
5	1		*FRONT HEADLAMP	Broken	0.00 F	*- F
6	1		*FRONT HEADLAMP BRACKET	Bent	0.00 F	*- F
7	1		*METER ASSY	Broken	0.00 F	*- F
8	1		*STEERING STEM	Necessary	0.00 F	*- F
9	1		*HANDLE BAR	Bent	0.00 F	*- F
10	1		*CLUTCH LEVER	Bent	0.00 F	*- F
11	1		*SIDE FAIRING	Cut	0.00 F	*- F
12	1		*FAIRING SHIELD	Cut	0.00 F	*- F
13	1		*EXHAUST MUFFLER HEAT SHIELD	Bent	0.00 F	*- F
14	1		*REAR BOX	Cut	0.00 F	*- F
15	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
16	1		*FRONT RIM	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >