

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20005172/KKA3Q2

Date: 27/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMP5459P	Insured Vehicle No :	SH6571L
Date of Loss: 06/04/2020	Nature of Claim: TP	Claim No: MCT20040099

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5459P		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C57993
Reg. Date:	30/09/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU003083717
Colour:	Metallic Red	Odometer:	38224 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,037.30	1,077.45	3,959.85	78.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,660.00	160.00	13,500.00	98.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,697.30	1,237.45	17,459.85	93.38
+ GST 7.00/7.00% (\$\$)	1,308.81	86.62	1,222.19	93.38
Nett Amount (\$\$)	20,006.11	1,324.07	18,682.04	93.38
+ Loss of Use (1.5 x S\$40.00/day) (\$\$)		60.00		
+ Car Rental (1.5 x S\$65.00/day) (\$\$)		97.50		
Nett Liability (\$\$)		1,481.57		
Global Sum Settlement (\$\$)		1,480.00		

INSPECTION

Date of Assignment:	13/04/2020	
Date Inspected:	13/04/2020	Inspected At:
		Trans-cab Auto Services Pte Ltd
		No 2 Ang Mo Kio St 63
		Singapore 569111
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5459P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY FRONT DOOR ,RH	Repair	1,300.70 FL	*- FL
2	1		*TAPE,BLACK OUT ,NO.1 FRT RH	Not Necessary	13.30 FL	*- FL
3	1		*TAPE,BLACK OUT ,NO.2 FRT RH	Not Necessary	43.50 FL	*- FL
4	1		*TAPE,BLACK OUT ,NO.3 FRT RH	Not Necessary	26.30 FL	*- FL
5	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Cracked	1,436.60 FL	*1,436.60 FL
6	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Repair	594.80 FL	*- FL
7	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	*- FS
8	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
9	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
10	1		*SET ROCKER PANEL MOULDING CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,891.10	1,436.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	853.80	359.15
Total Parts (\$\$)	5,037.30	1,077.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	80.00
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	60.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
9	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			13,660.00	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >