

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|--|---|---------------------|---------------|------------------------------|-------------------------|
| SOMPO INSURANCE SINGAPORE PL | | | Ref: | Ref: CS3/SMO20005174/R1yf3e2 | |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623 | | | Date: | 21-05-2020 | |
| | | | Code: | SMO | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| In | sured Veh. SMC 2738Y Veh. Inspected | | nspected | SLQ 3274A | |
| P | Policy No. | | Coverage (\$) | | 0.00 |
| С | laim No. | CMTD2001433/AGC | Excess (\$) | | 0.00 |
| A | ssign From | GRACE TEO | Assign | n Date | 13/04/2020 |
| 2. Vehicle Particulars & Condition | | | | | |
| М | ake & Model | HONDA STREAM 1.8L A | c.c | | 1799 |
| Eı | ngine No. | HIDDEN | Year of Reg. | | 2008 |
| С | hassis No. | JHMRN68408S201928 | Colour | | GREY |
| 0 | dometer | 271763 KM | Steering | | IN ORDER |
| В | rakes | IN ORDER | Modification | | SPORTS RIM |
| G | eneral | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| R | /H Front Tyre | 205/65 R15 | TOYO | | 6 mm |
| L/ | /H Front Tyre | 205/65 R15 | TOYO | | 6 mm |
| R | /H Rear Tyre | 205/65 R15 | TOYO | | 6 mm |
| L/ | /H Rear Tyre | 205/65 R15 | TOYO | | 6 mm |
| 4. Description of Damages | | | | | |
| Th | THE VEHICLE SUSTAINED DAMAGES AT THE REA | | | PORTION. | |
| 5. | General Information | | | | |
| A | ccident Date | 08/04/2020 | Inspec | t Date / Time | 14/04/2020 (11:50 AM) |
| S | urvey held at | ENG HUP SENG MOTOR | | | |
| | BLK 1 PANDAN LOOP #01-02 SINGAPORE 128219 | | | | |
| 5a. | Remarks | | | | |
| B) | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 | | | | |
| 5b. Estimate Days of Repair | | | | | |
| ES | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |

Report Ref No. CS3/SMO20005174/R1yf3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.