

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2019		06 Sep 2019 15:31 Edit Adj Rpt	S\$700.00 Edit Estimates	S\$700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured: Ride Now Private Limited , Co. Reg. No.: 201628643D																								
Main Claimant: CHAN HAN SHEEN , ID: S7672156D																								
Vehicle Reg. No.:	FU9975X	Date of Loss:	29/08/2019 00:00 - :59 [206 Months and 26 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 604948	Policy/Cover Note No.:	29032696TMC (Third Party Only) Coverage: 27/10/2018 - 26/10/2019																					
Vehicle Reg. No. (Insured):	SDS8232Y	Policy No. (Claimant):																						
		Excess:																						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/04/2020]																							
Adj Asg. Remarks:	on WP. Liab: NR. Disagree on SJE. Contact: Huiqin @ 8866 8832.																							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail MSIG_SG (13/04/2020): Report Send Back Alerts - FU9975X (TP)																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

***FU9975X (604948)**
[SDS8232Y]
TP
CHAN HAN SHEEN
Aug 29 2019 12:00AM
[Ride Now Private Limited]
My Car Consultant Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Photos/Images					
			3 per page ▼		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/09/19 12:45	General View		Load JPG	
2	19/09/19 12:45	General View		Load JPG	
3	19/09/19 12:45	General View		Load JPG	
4	19/09/19 12:45	General View		Load JPG	
5	19/09/19 12:45	General View		Load JPG	
6	19/09/19 12:45	General View		Load JPG	
7	19/09/19 12:45	General View		Load JPG	
8	19/09/19 12:45	General View		Load JPG	
9	19/09/19 12:45	General View		Load JPG	
10	19/09/19 12:45	General View		Load JPG	
11	19/09/19 12:45	General View		Load JPG	
12	19/09/19 12:45	General View		Load JPG	
13	19/09/19 12:45	General View		Load JPG	
14	19/09/19 12:45	General View		Load JPG	
15	19/09/19 12:45	General View		Load JPG	
16	19/09/19 12:45	General View		Load JPG	
17	19/09/19 12:45	General View		Load JPG	
18	19/09/19 12:45	General View		Load JPG	
19	19/09/19 12:45	General View		Load JPG	
20	19/09/19 12:45	General View		Load JPG	
21	19/09/19 12:45	General View		Load JPG	
22	19/09/19 12:45	General View		Load JPG	
23	19/09/19 12:45	General View		Load JPG	
24	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
25	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
26	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
27	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
28	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
29	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
30	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
31	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
32	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
33	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
34	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
35	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
36	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
37	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
38	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
39	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	
40	19/09/19 12:46	Photographs of Damaged Parts		Load JPG	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
42	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
43	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
44	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
45	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
46	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
47	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
48	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
49	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
50	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
51	19/09/19 12:46	Photographs of Damaged Parts		Load JPG ☒
52	09/04/20 13:43	After Repair Photo		Load JPG ☒
53	09/04/20 13:43	After Repair Photo		Load JPG ☒
54	09/04/20 13:43	After Repair Photo		Load JPG ☒
55	09/04/20 13:43	After Repair Photo		Load JPG ☒
56	09/04/20 13:43	After Repair Photo		Load JPG ☒
57	09/04/20 13:43	After Repair Photo		Load JPG ☒
58	09/04/20 13:43	After Repair Photo		Load JPG ☒
59	09/04/20 13:43	After Repair Photo		Load JPG ☒
60	09/04/20 13:43	After Repair Photo		Load JPG ☒
61	09/04/20 13:43	After Repair Photo		Load JPG ☒
62	09/04/20 13:43	After Repair Photo		Load JPG ☒
63	09/04/20 13:43	After Repair Photo		Load JPG ☒
64	09/04/20 13:43	After Repair Photo		Load JPG ☒
65	09/04/20 13:43	After Repair Photo		Load JPG ☒
66	09/04/20 13:43	After Repair Photo		Load JPG ☒
Documentation			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	06/09/19 10:13	PRI		Load PDF
2	06/09/19 10:13	TP GIA		Load PDF
3	06/09/19 10:32	Disagree on SJE		Load PDF
4	08/04/20 15:57	SDS8232Y		Load PDF
5	08/04/20 16:44	REPAIR BILL, SURVEY REPORT.pdf		Load PDF
6	08/04/20 16:45	SURVEY PHOTOS.pdf		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/04/20 15:25	PRS INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19015820/GSF3S2-1**Date:** 29/04/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29032696TMC
Claimant Vehicle No :	FU9975X	Insured Vehicle No :	SDS8232Y
Date of Loss:	29/08/2019	Nature of Claim:	TP
		Claim No:	604948

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FU9975X	Engine No:	TA200E0008959
Make & Model:	HONDA PHANTOM, 197cc	Chassis No:	TA2000008959
Reg. Date:	03/06/2002 (Man. Year: 2002)	Odometer:	94617 km
Colour:	Black		
Engine Capacity:	197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	130/90-15
Front Left Side:	Metzeler 4 mm	Rear Left Side:	Metzeler 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,775.60	567.00	5,208.60	90.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	300.00	1,240.00	80.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,315.60	867.00	6,448.60	88.15
Approved Total (Overridden) (S\$)		700.00		
Nett Amount (S\$)	7,315.60	700.00	6,615.60	90.43

INSPECTION

Date of Assignment:	06/09/2019		
Date Inspected:	06/09/2019	Inspected At:	KAKI BUKIT SYNERGY #01-68
Estimated Period of Repair:	3.0 days		Repairer: My Car Consultant Pte Ltd

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Apr 2020)	
Parts:	N/A	HONDA PHANTOM 197cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FU9975X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Cracked	650.00 FL	*95.00 FL
2	1		*FRONT HEADLAMP BRACKET	Serviceable	210.00 FL	*- FL
3	1		*FRONT SIGNAL LAMP RH	Serviceable	79.00 FL	*- FL
4	1		*FRONT FENDER	Cracked	250.00 FL	*50.00 FL
5	1		*BRAKE LEVER	Serviceable	150.00 FL	*- FL
6	1		*BALANCER	Serviceable	110.00 FL	*- FL
7	1		*RH FOOTREST	Serviceable	120.00 FL	*- FL
8	1		*RH FOOTREST BRACKET	Serviceable	230.00 FL	*- FL
9	1		*RH PILLION FOOTREST BRACKET	Not Necessary	210.00 FL	*- FL
10	1		*WING MIRROR	Not Necessary	110.00 FL	*- FL
11	1		*FUEL TANK	Dented	920.00 FL	*485.00 FL
12	1		*HANDLE BAR	Not Necessary	350.00 FL	*- FL
13	1		*HANDLE BAR GRIP	Not Necessary	110.00 FL	*- FL
14	1		*FRONT LH FORK ASSY	Serviceable	550.00 FL	*- FL
15	1		*FRONT RH FORK ASSY	Serviceable	550.00 FL	*- FL
16	1		*STEERING HEADCROWN	Serviceable	210.00 FL	*- FL
17	1		*STEERING STEM UNDERBRACKET	Serviceable	95.00 FL	*- FL
18	1		*STEERING STEM BEARING	Serviceable	120.00 FL	*- FL
19	1		*REAR EXHAUST	Serviceable	650.00 FL	*- FL
20	1		*SET GEAR SHIT SHAFT OIL SEAL	Serviceable	12.00 FS	*- FS
21	2		*FORK OIL SEAL	Serviceable	45.00 FS	*- FS
22	1		*BOT FORK OIL	Serviceable	12.00 FS	*- FS
23	1		*REAR BOX	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,343.00	630.00
- List Item Discount on L Items 10.00/10.00% (S\$)	567.40	63.00
Total Parts (S\$)	5,775.60	567.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM.	New	600.00	150.00
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING.	New	380.00	0.00
3	TO REMOVE / RFEFIT, REPLACE FRONT FORK TUDES.	New	180.00	0.00
4	SPRAY PAINTING.	New	380.00	150.00
Gross Labour Cost (\$\$)			1,540.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >