

149

53, Ubi Avenue 1, Paya Ubi Industrial Park  
#01-33, Singapore 40934

CHAN HAN SHEEN	
----------------	--

<b>Invoice No.</b>	MYCAR/19/402
<b>Our Ref.</b>	FU9975X
<b>Your Ref.</b>	
<b>Date</b>	15 October 2019

Authorised Signatory

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647.Singapore 542224

Email: [Winsongkk@hotmail.com](mailto:Winsongkk@hotmail.com) Contact: 9747 0063

Company Register No. 53326249J

---

Our Ref: WG/TP/2019-402  
Invoice No: TP/MCC/2019-402  
Vehicle No: FU9975X  
Attn: CHAN HAN SHEEN  
Company: MY CAR CONSULTANT PTE LTD  
Address: 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

Date 15 October 2019

## Invoice

Surveyor Fee: S\$270  
Re-inspection Fee: S\$50  
Transport: S\$50  
Photographs: S\$51/- (@ \$1 per photo, total 51 photos)  
Total: S\$421

Surveyor: Winsong Goh  
Signature:   
Date: 15 October 2019



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : CHAN HAN SHEEN  
C/O MY CAR CONSULTANT PTE LTD  
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park  
Singapore 408934

Date : 15 October 2019  
Our Ref : WG/TP/2019-403

### REFERENCE PARTICULARS

Date of Accident : 29 August 2019  
Date of Inspection : 06 September 2019

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 10 September 2019

### VEHICLE PARTICULARS

Registration No : FU9975X  
Make : HONDA  
Model : PHANTOM  
Year : 2002

Engine No : TA200E0008959  
Chassis No : TA2000008959  
Odometer : 94617km  
Colour : Black

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front side	: Metzeler	180/80-17
Rear Side	: Metzeler	130/90-15

<u>Thread Balance</u>
5 mm
5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$4,700.00** nett at lump sum basis. (Subject to GST if applicable)  
Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Fifty-one ( 51 ) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD  
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

In accordance to your instruction, we have **not authorise** repairs and inspection  
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : FU9975X  
MODEL : PHANTOM

Our Ref : WG/TP/2019-402

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS**

**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION		ORIGINAL QUOTATION	REVISED QUOTATION
1	FRONT HEADLAMP	1	CRACKED	\$	650.00	\$ 650.00
2	FRONT HEADLAMP BRACKET	1	NOT NECESSARY	\$	210.00	\$ -
3	FRONT SIGNAL LAMP RH	1	CRACKED	\$	79.00	\$ 79.00
4	FRONT FEDNER	1	CRACKED	\$	250.00	\$ 250.00
5	BRAKE LEVER	1	GRAZED	\$	150.00	\$ 150.00
6	BALANCER	1	GRAZED	\$	110.00	\$ 110.00
7	RH FOOTREST	1	BENT	\$	120.00	\$ 120.00
8	RH FOOTREST BRACKET	1	BENT	\$	230.00	\$ 230.00
9	RH PILLION FOOTREST BRACKET	1	NOT NECESSARY	\$	210.00	\$ -
10	WING MIRROR	1	NOT NECESSARY	\$	110.00	\$ -
11	FUEL TANK	1	DENTED	\$	920.00	\$ 920.00
12	HANDLE BAR	1	NOT NECESSARY	\$	350.00	\$ -
13	HANDLE BAR GRIP	1	NOT NECESSARY	\$	110.00	\$ -
14	FRONT LH FORK ASSY	1	BENT	\$	550.00	\$ 550.00
15	FRONT RH FORK ASSY	1	BENT	\$	550.00	\$ 550.00
16	STEERING HEADCROWM	1	NECESSARY	\$	210.00	\$ 210.00
17	STEERING STEM UNDERBRACKET	1	NECESSARY	\$	95.00	\$ 95.00
18	STEERING STEM BEARING	1	NECESSARY	\$	120.00	\$ 120.00
19	REAR EXHAUST	1	GRAZED	\$	650.00	\$ 650.00
				\$	5,674.00	\$ 4,684.00
				Less 10%	\$ 576.40	\$ 468.40
					<u>\$ 5,097.60</u>	<u>\$ 4,215.60</u>
B)	<u>S/NETT ITEM</u>					
20	GEAR SHIT SHAFT OIL SEAL	1 SET	NECESSARY	\$	12.00	\$ 12.00
21	FORK OIL SEAL	2	NECESSARY	\$	45.00	\$ 45.00
22	FORK OIL	1 BOT	NECESSARY	\$	12.00	\$ 12.00
23	REAR BOX	1	GRAZED	\$	600.00	\$ 500.00
				\$	<u>669.00</u>	<u>\$ 569.00</u>
			Parts Total :	\$	<u>5,766.60</u>	<u>\$ 4,784.60</u>
C)	<u>LABOUR CHARGES &amp; MISC</u>					
24	REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM			\$	600.00	\$ 400.00
25	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING			\$	380.00	\$ 250.00
26	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES			\$	180.00	\$ 150.00
27	SPRAY PAINTING			\$	380.00	\$ 300.00
			Labour Total :	\$	<u>1,540.00</u>	<u>\$ 1,100.00</u>
			Total Parts and Laboure :	\$	<u>7,306.60</u>	<u>\$ 5,884.60</u>
	<u>FINAL LUMP SUM ADJUSTMENT</u>					<u>\$ 4,700.00</u>

#### POINT OF IMPACT

The impact was confined to the front left portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$4,700.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES



Winson Goh  
Automotive Appraiser